

MC6-WS

Advanced Workshop Calibrator and Communicator



Applies to firmware version 5.20

Dear user,

We have made every effort to ensure the accuracy of the contents of this manual. Should any errors be detected, we would greatly appreciate to receive suggestions to improve the quality of the contents of this manual.

For more information on the Beamex MC6 Advanced Workshop Calibrator and Communicator, please visit the MC6-WS product page on Beamex website.

© Beamex 2025

Beamex Oy Ab

Ristisuonraitti 10

FIN-68600 Pietarsaari

Finland

Tel: +358-10-5505000

E-mail: sales@beamex.com

service@beamex.com

Website: <https://www.beamex.com>

Table of Contents

Prologue.....	6
Unpacking and Inspection.....	6
About This Manual.....	7
Typographical Conventions.....	8
Safety.....	9
Certifications.....	9
Safety Symbols.....	9
Safety Precautions and Warnings.....	10
Warnings Concerning Electrical Measurement and Generation.....	11
Warnings Concerning Pressure.....	11
Warnings Concerning High Pressure.....	12
Warnings Concerning Smart Instruments.....	13
Warnings Concerning the Lithium-ion Battery Pack.....	14
Specifications.....	17
About MC6-WS.....	19
Hardware Overview.....	19
Pressure Modules.....	21
Memory and Data Management.....	24
Display.....	25
Battery and Charging.....	25
Checking Battery Level and Charging Status.....	25
Charger and Charging Procedure.....	26
Power Management.....	26
User Interface.....	28
Home View and User Interface Modes.....	29
Interacting with MC6-WS.....	30
Editable Fields.....	32
Calibration Management Software.....	37
Communicating with LOGICAL.....	37
Communicating with CMX.....	37
Options, Accessories and Services.....	37
Software Options.....	38
Accessories and Related Products.....	39
Services.....	39
Available PC Tools.....	39
Calibration Capabilities and Connections.....	40
Measurements.....	41
Pressure Measurement.....	41

User-Defined Pressure Units.....	43
Connecting and Disconnecting External Pressure Modules...	44
Temperature Measurement (RTD).....	45
Temperature Measurement (Thermocouple).....	46
Resistance Measurement.....	47
Current Measurement.....	48
Voltage Measurement.....	49
Frequency Measurement.....	50
Pulse Counting.....	51
Switch Sensing.....	53
Electrical Generations and Simulations.....	54
RTD Simulation.....	54
Thermocouple Simulation.....	55
Resistance Simulation.....	56
Current Generation (Source or Sink).....	57
Voltage Generation.....	58
Frequency Generation.....	59
Pulse Generation.....	60
Smart Instrument Connections.....	61
Thermocouple Connections.....	62
Meter.....	65
Calibrator.....	67
Documenting Calibrator.....	69
Calibration Process with MC6-WS.....	70
Instrument Data.....	70
Calibration Execution and Calibration Results.....	71
Instrument List.....	72
Plant Structure Levels.....	75
Instrument List Menu.....	75
Instrument Overview Window.....	77
Calibrating an Instrument.....	78
Calibration Point Acceptance.....	80
Calibration Results Window.....	82
Viewing Saved Calibration Results.....	85
Deleting Calibration Results.....	86
Creating Instruments in MC6-WS.....	86
Identification Related Data.....	87
Instrument Function Related Data.....	88
Calibration Procedure Related Data.....	92
Error Limit Related Data.....	94
Device Related Data.....	95
Group Calibration.....	96
Creating and Editing a Group.....	96
Calibrating a Group.....	99
Group Settings.....	101

Special Use Cases.....	102
Changing a Pressure Module During Calibration.....	102
Using External Controllers in Calibration.....	103
Changing a Controller During Calibration.....	103
Work Order View Mode.....	104
Mobile Security Plus Option.....	106
Data Logger.....	108
Configuring a Data Log.....	108
Logging Data.....	112
Data Log Results.....	113
Viewing Saved Data Log Results.....	114
Data Log Viewer.....	115
Communicator.....	117
Device Description Files.....	118
Basic View.....	122
Managing Smart Instrument Configurations in MC6-WS.....	123
Saving Configurations.....	124
Viewing or Opening Configurations.....	125
Linking Configurations to CMX.....	126
Working With Smart Instruments.....	127
About Smart Instrument Parameters.....	128
Editing Parameters.....	130
Selecting Instruments.....	131
List of Found Devices.....	132
Get Mapped Values feature.....	133
Preparations.....	134
Mapping the Instrument Data.....	134
Customizing the Mappings.....	135
Calibrating Smart Instruments.....	139
Calibrating or Data Logging HART Instruments.....	139
Calibrating or Data Logging Fieldbus Instruments.....	141
Trimming Smart Instruments.....	143
Trimming a HART Instrument.....	143
Trimming a Fieldbus Instrument.....	145
Advanced Features.....	147
Tools.....	147
User-Defined Transfer Functions.....	151
User-Defined Steps/Calibration Points.....	153
User Sensors.....	155
Creating a New User Sensor.....	156
Using User Sensor.....	158
Updating User Sensor Data.....	159
Callendar-Van Dusen Formula.....	159
ITS-90.....	160

Factor.....	162
Check Sensor Conversion.....	163
Controller Communication.....	164
Enabling Communication with the Controller.....	164
Calibration Methods with External Controllers.....	167
Wireless Communication.....	168
Connection Security.....	169
Requirements.....	169
Enabling Communication with a Client Device.....	170
Information Window.....	172
Troubleshooting.....	174
Settings.....	176
Maintenance.....	179
Cleaning Instructions.....	179
Firmware Update.....	180
Replacing the Battery Pack.....	181
Teaching the Battery.....	182
Recalibrating and Adjusting MC6-WS.....	183
Recalibrating the Calibrator.....	183
Calibration and Adjustment Instructions.....	183
Changing Calibration Date and Interval.....	184
Adjusting the Calibrator.....	184
Preparing the MC6-WS for Service Returns.....	184
Resetting the Calibrator.....	185
Installing and Uninstalling Modules in CENTRiCAL.....	186
Disposing of Waste Electrical and Electronic Equipment.....	186
Disposing the Battery Pack.....	187
Index.....	191

Prologue

Thank you for buying Beamex MC6-WS Advanced Workshop Calibrator and Communicator.

The Beamex MC6-WS is a reliable and stable, high-accuracy, panel-mounted workshop calibrator and communicator, that combines advanced functionality with ease-of-use. The MC6-WS is the heart of the Beamex CENTRiCAL Workshop Calibration Solution. The main features of MC6-WS are its advanced functionality, enhanced usability and fully digitalized calibration process.

MC6-WS offers calibration capabilities for pressure, temperature, and various electrical signals. It also contains a multi-bus field communicator for HART, FOUNDATION Fieldbus H1, and Profibus PA protocols, allowing you to calibrate, configure, and trim your smart instruments.

It includes several intuitive user interface modes, optimized for different use cases and available in multiple languages. The calibrator guides you step by step through your calibration work and can even perform fully automatic calibrations.

Additionally, the MC6-WS is a documenting calibrator that communicates with Beamex Calibration Management Software, enabling a fully digitalized calibration process.

Unpacking and Inspection

At the factory, each new MC6-WS passes a careful inspection. It should be free of scrapes and scratches and in proper working order upon receipt. The receiver should, however, inspect the unit for any damage that may have occurred during transportation. If there are signs of obvious mechanical damage, package contents are incomplete, or it does not operate according to specifications, contact your Beamex representative as soon as possible.

A leaflet listing all standard accessories is included in the package. To verify the contents of your delivery, please check the leaflet.

About This Manual

The MC6-WS User Manual is divided into several parts as follows:

- **Safety** - explains how to ensure safe use of the calibrator. Read the warnings carefully before using the calibrator.
- **Specifications** - includes information about the operating conditions and specifications of the calibrator.
- **About MC6-WS** - provides an overview of the calibrator's hardware and software. It also explains how calibration capabilities can be expanded by utilizing other Beamex products and services, as well as battery, charger, and power management information.
- **Calibration Capabilities and Connections** - describes all the measurement, simulation and generation functions the calibrator supports. It also explains how to make the necessary connections to the calibrator's terminals.
- **Meter** - introduces the user interface mode designed for quick and easy signal measurement.
- **Calibrator** - presents the user interface mode for calibrating various process instruments. It allows you to measure, simulate, or generate two signals at a time.
- **Documenting Calibrator** - explains the user interface mode for documented and automated calibration of various types of process instruments. Use the Documenting Calibrator together with Beamex LOGiCAL or CMX Calibration Management Software to fully benefit from the digitalized calibration process.
- **Data Logger** - describes the optional user interface mode designed for logging various measurement results over shorter or long periods of time.
- **Communicator** - outlines the user interface mode for viewing and editing the configuration of HART, FOUNDATION Fieldbus H1, or Profibus PA smart instruments.
- **Working With Smart Instruments** - explains how to use your smart instruments in various user interface modes of the MC6-WS.
- **Advanced Features** - introduces various functionalities of the MC6-WS that support your calibration process.
- **Settings** - presents how to edit different settings of the calibrator.
- **Maintenance** - provides a description of maintenance actions that can be performed by the user.

Typographical Conventions

The following typographical conventions apply to the MC6-WS User Manual:

Bold text is typically used in cases like:

- keywords, such as terms and User Interface buttons
- other keywords, for example, fieldbus parameters



Note: This is a note. Notes typically provide important information to consider and remember.



Tip: This is a tip. Tips offer useful advice or practical information related to the current topic.



Caution: This is a caution. Cautions highlight situations that could result in damage to the calibrator if not observed. Always read cautions carefully and follow the instructions.



Warning: This is a warning. Warnings indicate situations that could cause serious injury or damage if not followed. Always read warnings carefully and comply with them to ensure safety.

Safety

MC6-WS calibrator is a precision tool intended for use by skilled personnel who have read and understood this manual. Working with the MC6-WS involves the use of pressure, electrical and/or temperature instruments. Make sure to know how to handle these instruments safely, including how to connect and disconnect pressure hoses, electrical test leads clips, and other accessories.

Use the MC6-WS calibrator only if you are confident that it can be operated safely. Safe use of the MC6-WS is no longer possible if any of the following cases are true:

- The enclosure of the MC6-WS is visibly damaged.
- The MC6-WS is not functioning as expected.
- There is an unusual smell coming from the unit's battery.
- The calibrator has been stored for a prolonged period under unfavorable conditions.
- The calibrator has suffered serious damage during transportation.

Certifications

The MC6-WS complies with the EMC Directive and Low Voltage Directive. The EU Declaration of Conformity and the UK Declaration of Conformity contain approvals, certificates, and detailed standard references. The declarations are available under the Resources tab on the [MC6-WS page](#) on the Beamex website.

Safety Symbols

The following safety-related symbols are used on the MC6-WS.

	Alternating current, AC
	Direct current, DC
	Caution! See manual for further information

Safety Precautions and Warnings



Caution: Read and fully understand this manual and all other safety instructions before operating the Beamex MC6-WS Advanced Workshop Calibrator and Communicator.



Warning: Do not use the MC6-WS in any way other than as described in this user manual. Using the calibrator in a manner not specified by the manufacturer may impair the protection it provides against hazards.



Caution: Only qualified and trained personnel are allowed to use the MC6-WS. Incorrect use may result in damage to the calibrator and/or personal injury.



Warning: Only use the calibrator for purposes and in environments specified in the user manual.



Note: If the calibrator has been stored in different environment, allow it to stabilize to new environment before use.



Warning: Do not tap the touch screen with sharp or hard objects or press hard on the display, especially with fingernails. Instead, tap lightly using your fingertips.



Note: For all measurement ports except IN and OUT, use cables not longer than 3 m.



Note: Sometimes it is necessary to use a portable radio transceiver while working with the calibrator. To prevent calibration errors caused by radio frequency interference, keep the radio at least 1 m away from the calibrator and the circuit under calibration while transmitting.

Warnings Concerning Electrical Measurement and Generation



Warning: All MC6-WS terminals are protected against overvoltage and overcurrent as far as possible without affecting accuracy. Do not connect signals that exceed the measurement range of the selected function.

The maximum output voltage from MC6-WS terminals is below 30 V. However, if you connect voltages from both the IN and TC-R-OUT sections together, or connect external voltages to the MC6-WS, the resulting voltage may be high enough to be hazardous.

There is no galvanic isolation between the IN section connectors and the pressure module connectors connected to the CENTRiCAL Instrument Panel.

Although there is a galvanic isolation between the MC6-WS IN and TC-R-OUT sections, it is intended for functional purposes only. Do not exceed 60 V DC / 30 V AC / 100 mA between any terminals.

Functional insulation is not intended for protection against transient overvoltages. Do not connect measuring terminals to circuits where transient overvoltages may occur.

Warnings Concerning Pressure



Warning: Never exceed the maximum pressure of a pressure module. The maximum pressure is indicated on the module's sticker or in the user manual. Never exceed the maximum allowable pressures of optional pressure hoses.

Applying pressure above these limits can be hazardous.

We recommend using Beamex pressure hoses, fittings and optional pressure hose sets. If using other hoses or fittings, ensure they are of high quality and withstand the applied pressure.



Warning: Always depressurize the system before opening or connecting any pressure fittings or connectors. Use appropriate venting valves and ensure all connections are correct, with hoses and connectors in good condition.



Warning: For external pressure modules, always use the pressure media specified on the module:

- 6 bar (90 psi) and lower: dry, clean, inert, non-toxic, non-corrosive gases.
- 20 bar (300 psi) and higher: clean, inert, non-toxic, non-corrosive gases or liquids.

Use of the wrong type of pressure media may destroy the pressure module or calibrator.



Caution: Avoid spilling liquid on the MC6-WS when connecting or disconnecting pressure hoses to or from pressure modules.



Warning: Pressure modules with a measuring range of 6 bar (90 psi) and lower are equipped with overpressure protection. If the measurement pressure of a pressure module exceeds the module's maximum pressure value, the overpressure protector vents excess pressure through a hole in the back of the enclosure.



Caution: To avoid damaging the pressure module or the calibrator, tighten the pressure measurement hoses by hand only (max. torque 5 Nm, approx. 3.6 lbf ft). If the use of tools is required to secure the connection (typically for pressure modules with a pressure range higher than 20 bar (300 psi)), apply counterforce by placing a 14 mm (approx. 9/16") spanner on the flats found in the module's connector. The overpressure protection of the internal pressure modules vents to the inside of the module rack.



Warning: Never plug a hose with your hands or place your hands in front of a gas spray coming from a leak. A gas bubble in the bloodstream can be fatal.

Warnings Concerning High Pressure



Warning: High pressure is always dangerous. Only personnel with sufficient experience and knowledge of high-pressure liquid, air, and nitrogen operations are permitted to work with the pressure module. **Carefully** read these instructions and familiarize yourself with local safety regulations for high-pressure operations before starting use.



Warning: When using gas, ensure that the system does not contain any liquid, especially if you do not know how it may react under pressure. Use of clean air or nitrogen is recommended as the gaseous pressure media. Liquid pressure media should be preferred when using modules with a pressure range of 60 bar (30,000 psi) and higher.



Warning: If you use nitrogen, minimize the leakage to the atmosphere and ensure sufficient ventilation. Close the valve of the nitrogen cylinder, when the system is not in use. An increase in the percentage of nitrogen in the ambient air may cause unconsciousness and death without warning. **Carefully** read the safety instructions for nitrogen and make sure that other people in the same space are aware of the danger.

Use of liquid pressure medium is recommended with pressure measurement modules at higher pressure ranges. Use water or suitable hydraulic oil. Check that the liquid used is not aggressive against the materials of the transducer or tubing. When using liquid, minimize the amount of air in the system. This way you can minimize the amount of spilled liquid in case of leakage.



Warning: Do not use the same hoses with different liquids or gases. Check the local regulations regarding the construction and use of pressurized vessels. The regulations usually apply to systems where the product of the pressure and volume exceeds a certain limit. The volume of the system depends on the instrument connected to it.

High-pressure gas is dangerous because it can break the container, and the flying splinters may cause injury. Also, small leaks of gas may be dangerous because the high velocity of the leaking gas jet enables penetration through skin. If a gas bubble gets into the bloodstream, it can cause death. The leak jet is particularly dangerous if some liquid is coming with the gas.

Warnings Concerning Smart Instruments



Warning: Configuring or calibrating an instrument while it is a part of a live segment is possible only with HART and FOUNDATION Fieldbus H1. When working on a live segment, first ensure that the control loop the instrument belongs to is set to manual. Always follow the instructions provided in the instrument's own manual.

Beamex is not responsible for any damage caused by connecting an MC6-WS to a live factory fieldbus segment.



Warning: When working in PROFIBUS PA, never connect two master devices (e.g. MC6-WS, a Field Communicator, or a control system) to the same segment at the same time. This will cause conflicts and make the fieldbus segment unstable. Always remove the instrument to be calibrated from the live segment before calibration.



Warning: Using an MC6-WS to change instrument parameters may cause discrepancies, as a fieldbus host control system may mirror all instrument parameters in its permanent database. In such cases, when returning an instrument with changed parameters to a live segment, make sure the updated parameters are also entered into the control system's permanent database. Additionally, confirm that the new parameters do not lead to an unstable control loop.

Warnings Concerning the Lithium-ion Battery Pack

General Safety



Warning: The Lithium-ion (Li-ion) battery pack requires careful and responsible handling. To prevent accidents or damage to people or property, always follow the safety precautions and warnings provided in this user manual. The battery pack is intended for use exclusively with the Beamex MC6-WS. Using it in any other application may be hazardous.



Warning: Always use the battery pack supplied by Beamex. Using battery packs not intended for MC6-WS is dangerous. When replacing the battery, ensure the polarity is correct. Never short-circuit the battery pack. A short-circuit can burn you, damage equipment, or even cause a fire. Keep in mind that new replacement battery pack are also shipped in a charged state.

Ignoring these warnings could lead to an explosion.



Warning: Never leave the battery pack in a car on a hot day, in direct sunlight, or near any heat source. Excessive heat reduces performance and may cause the battery pack to ignite or explode.



Warning: Do not use the battery pack if it emits an unusual smell, becomes hot, deforms, or behaves abnormally in any way. Always check the battery's condition, especially if the MC6-WS has been dropped or subjected to impact.



Warning: Never disassemble the battery pack. It contains safety and protection electronics and damaging them could cause overheating, fire, or an explosion.



Warning: If the battery leaks and fluid comes into contact with your skin, wash the affected area thoroughly with soap and water. If the fluid gets into your eyes, rinse immediately with plenty of cold water and seek medical attention.



Warning: If the battery pack catches fire, use plenty of water to cool it down and extinguish the fire.



Warning: Do not expose battery to water, salt water, or allow it to get wet.

Charging and Charger Safety



Warning: Charge the battery pack only with the charger provided for MC6-WS (BC15). The battery is located inside the MC6-WS. Never leave the MC6-WS unattended while charging, and always charge it away from flammable materials.



Warning: Use the charger in clean, dry environments such as laboratories or offices, where dust and humidity are limited.



Warning: If the battery pack starts to heat up or deform during charging, stop immediately and disconnect the charger. Move the MC6-WS to a fireproof area and wait about 15 minutes. If no further issues occur, you can attempt to charge it again while closely monitoring the process. It is safer to replace a faulty battery pack than risk serious damage.



Warning: If the battery fails to recharge within the specified time, stop charging immediately. The expected charging time is approximately 4 hours for a 4300 mAh battery pack.



Warning: After long periods of storage, you may need to charge and discharge the battery several times to restore its maximum performance.

Battery Pack Replacement



Warning: Always replace the battery pack with a new one purchased directly from Beamex or an authorized Beamex representative. For details, visit the [Beamex Webshop](#).



Warning: Do not replace the battery pack with any other type. Using unauthorized battery packs may make the MC6-WS unsafe and could result in fire or explosion. It will also void the warranty.

Battery Pack Disposal



Warning: The MC6-WS battery pack is classified as hazardous waste. Dispose of used batteries responsibly and according to local regulations.

Never crush, short-circuit, or incinerate battery cells under any circumstances.

Specifications

Each MC6-WS is delivered with a traceable, accredited calibration certificate as standard, providing proof of its accuracy.



Note: Accuracy specifications for all measurement, generation, and simulation functions can be found under the Specifications tab on the [MC6-WS page](#) on the Beamex website.

Table 1: General Specifications

FEATURE	VALUE
Display	5.7" Diagonal 640 x 480 TFT LCD module
Touch panel	5-wire resistive touch screen
Operating temperature	0 ... 45 °C (32 ... 113 °F)
Operating temperature during battery charging	0 ... 45 °C (32 ... 113 °F)
Operating humidity	0 ... 80 % R.H. non condensing
Storage temperature	-20 ... 60 °C (-4 ... 140 °F)
Max. altitude	3000 m (approx. 9,800 ft)
Max. input voltage	30 V AC, 60 V DC

Table 2: Battery Pack Specifications

FEATURE	VALUE
Battery pack type	Rechargeable lithium-ion battery, 4300 mAh, 11.1 V
Charging time	Approximately 4 hours
Charger supply	100 ... 240 V AC, 50 ... 60 Hz
Battery pack operation	10 ... 16 hours
Battery pack storage temperature (charged 30%)	≤ 1 month: -20 ... 45 °C (-4 ... 113 °F) > 3 months: -20 ... 30 °C (-4 ... 86 °F)



Warning: When transporting or temporarily storing the MC6-WS battery pack, store it at approximately 30% charge. Storing the battery fully charged or fully discharged can lead to significant capacity loss or possible malfunction of the protection electronics.



Note: If MC6-WS is not in use for an extended period, it is recommended to recharge it every 3 months.

Specifications are subject to change without prior notice. For the latest technical information, visit the [MC6-WS page](#) on the Beamex website.

About MC6-WS

Hardware Overview

MC6-WS - Main View




Figure 1: MC6-WS, overview

Legend:

1. **Thermocouple** and **Millivolt** port (TC1) with release buttons. The port is designed for cables and standard TC plugs.
2. **Thermocouple** and **Millivolt** port (TC2). The port accommodates TC plugs with flat contacts.
3. **RTD** and **Resistor** terminals (R1).
4. **Voltage**, **Current**, and **Frequency** output (OUT).

5. **Voltage, Frequency, and Switch** input (**IN**).
6. **Current Measurement, Loop Supply, and Smart instrument** (HART and fieldbus) terminal (**IN**).
7. Connector for **External Pressure Modules (PX)**.
8. **Enter** button — selects the item surrounded by the hardware focus indicator.
9. **Arrow** buttons — press once to display the hardware focus indicator.
10. **Home** button — press to return to Home View.
11. **R2** connector. Provides the possibility to connect an external RTD sensor to MC6-WS.
12. **Power** button.
13. Two **USB-A** ports for connecting various USB devices, such as external controllers and a Bluetooth adapter, to MC6-WS.

MC6-WS - Rear View (Inside the CENTRiCAL Instrument Panel)




Figure 2: Connectors at the back of MC6-WS

Legend:

1. Two USB-B port with isolation.
2. One USB-B port without isolation.
3. Connector for pressure modules in the CENTRiCAL.
4. Two **USB-A** ports for connecting various USB devices, such as external controllers and a Bluetooth adapter, to MC6-WS.
5. **Power** connector for charging the calibrator.



Note: An isolated USB hub inside the CENTRiCAL Instrument Panel provides more USB connectors than the portable MC6.




Figure 3: Default connections inside CENTRICAL – top view of MC6-WS

When the MC6-WS is installed in a CENTRICAL bench, additional calibrator USB sockets are available in the Instrument Panel, located at the rear of the tabletop under the standard flaps. One USB socket (**PC to MC6-WS**) is for PC communication with the calibrator, and another (**POC8 to MC6-WS**) is for connecting the calibrator to the POC8. If the MC6-WS is installed in another CENTRICAL solution (e.g. trolley), the USB sockets are positioned at the back of the Instrument Panel.



Figure 4: USB socket location – rear view of the Instrument Panel

Pressure Modules

Beamex offers a wide range of internal and external pressure modules for MC6-WS, covering pressure ranges from barometric up to 1000 bar. Panel-mounted pressure modules are installed in the Instrument Panel of CENTRICAL calibration bench, trolley, or tabletop solutions. All of these modules have a panel-width of 0.5 MP (Module Place). The MC6-WS can hold up to ten panel-mounted modules, which are connected internally via a daisy-chain communication cable inside the CENTRICAL. **EXT CENTRICAL** modules are panel-mounted external pressure modules compatible with all Beamex

multifunction calibrators. In the MC6-WS User Interface, pressure modules are labeled as **Pn: P1C**, where:

- **n** refers to the location of a pressure module.
- **P1C**, and similar, represent the pressure module types.




Figure 5: Example of set of pressure modules in CENTRiCAL

In addition to the internal modules, one external module can be connected to the calibrator at a time using the PX connector and a communication cable.

Barometric Pressure Module

In the MC6-WS User Interface, barometric pressure modules appear as **PB**: **PB**. The connection in front of a barometric module is intended for calibration use only. To maintain valid barometric pressure measurements, avoid using the connection unless calibrating the module.

More details are available in chapter [Installing and Uninstalling Modules in CENTRiCAL](#).

Table 3: Available pressure measurement module types and their measurement ranges

Internally connected modules	Externally connected modules	Range	Pressure connection
PB	EXTB	70 ... 120 kPa a 700 ... 1200 mbar a 10.15 ... 17.4 psi a	10/32" (M5) female

Internally connected modules	Externally connected modules	Range		Pressure connection
P10mD	EXT10mD	±1 ±10 ±4	kPa diff mbar diff iwc diff	2 x adapters for 1/8" ID hose (3,2 mm)
P100m	EXT100m	0 ... 10 0 ... 100 0 ... 40	kPa mbar iwc	Bx G1/8" male compatible with Beamex 40 bar hoses
P400mC	EXT400mC	±40 ±400 ±160	kPa mbar iwc	Bx G1/8" male compatible with Beamex 40 bar hoses
P1C	EXT1C	±100 ±1 -14.5 ... 15	kPa bar psi	Bx G1/8" male compatible with Beamex 40 bar hoses
P2C	EXT2C	-100 ... 200 -1 ... 2 -14.5 ... 30	kPa bar psi	Bx G1/8" male compatible with Beamex 40 bar hoses
P6C	EXT6C	-100 ... 600 -1 ... 6 -14.5 ... 90	kPa bar psi	Bx G1/8" male compatible with Beamex 40 bar hoses
P20C	EXT20C	-100 ... 2000 -1 ... 20 -14.5 ... 300	kPa bar psi	Bx G1/8" male compatible with Beamex 40 bar hoses
P60	EXT60	0 ... 6000 0 ... 60 0 ... 900	kPa bar psi	<u>P60</u> : Bx 1215 male compatible with Beamex 630 bar hoses <u>EXT60</u> : G1/4" B male
P100	EXT100	0 ... 10 0 ... 100 0 ... 1500	MPa bar psi	<u>P100</u> : Bx 1215 male compatible with Beamex 630 bar hoses <u>EXT100</u> : G1/4" B male

Internally connected modules	Externally connected modules	Range		Pressure connection
P160	EXT160	0 ... 16 0 ... 160 0 ... 2400	MPa bar psi	P160: Bx 1215 male compatible with Beamex 630 bar hoses EXT160: G1/4" B male
P250 available for MC6-WS	EXT250	0 ... 25 0 ... 250 0 ... 3700	MPa bar psi	G1/4" B male
P600 available for MC6-WS	EXT600	0 ... 60 0 ... 600 0 ... 9000	MPa bar psi	G1/4" B male
-	EXT1000 (portable only)	0 ... 100 0 ... 1000 0 ... 15,000	MPa bar psi	G1/4" B male



Note: Use caution when working with pressure and pressure modules. For more information, see chapter [Warnings Concerning Pressure](#).

Memory and Data Management

The MC6-WS can safely store a large amounts of data, such as instruments, calibration results, and data logs. The data is stored on solid-state memory that preserves information without requiring power. This shockproof memory ensures that no data is lost even if the calibrator is damaged.

All data is stored locally on the MC6-WS. The calibrator does not transmit any user-entered or generated data to Beamex.

You can erase all data with a factory reset. For more information, see chapter [Resetting the Calibrator](#).



Caution: Deleted data cannot be recovered.

Display

The MC6-WS features a backlit 5.7" TFT LCD display with a resolution of 640×480 pixels and a responsive touch panel. You can operate the touch screen with your fingers, whether wearing gloves or not. Optionally, use a stylus designed for touch screens.



Tip: For brightness adjustments, see chapter [Settings](#).



Warning: Do not tap the touch screen with sharp or hard objects, and avoid pressing hard on the display, especially with fingernails. Always tap gently with your fingertips. Using sharp tools like screwdrivers can damage the screen.

Battery and Charging

The MC6-WS internal Lithium-ion (Li-ion) battery pack enables continued use of MC6-WS even when CENTRiCAL is shut down. It also maintains the internal clock and calendar when the CENTRiCAL is powered off. When CENTRiCAL is on, the battery is automatically charged via its power supply. Li-ion battery can be charged at any time as it does not experience memory effect.



Note: For detailed battery safety instructions, refer to chapter [Warnings Concerning the Lithium-ion Battery Pack](#).

Checking Battery Level and Charging Status

An icon indicating battery level (or a plug when the battery is full) is visible in several user interface views.



Figure 6: Battery level icons

Battery operating time without recharging varies based on the use of the display backlight and transmitter supply voltage. Under constant full load, the standard rechargeable batteries should provide approximately 10 hours of use. In typical conditions, an average operating time of 16 hours can be expected.

Battery capacity naturally decreases over time. If the MC6-WS internal clock resets, the battery pack should be replaced.



Note: An approximate time (hh:mm) appears on the battery icon:

- **Charging time remaining** — while charging
- **Operating time remaining** — while running on battery

For detailed battery and charging status, tap the battery icon.



Caution: The MC6-WS internal clock and calendar consume a small amount of power even when the CENTRiCAL or MC6-WS is switched off. Check the battery capacity periodically, even if the MC6-WS is not being used. Recharge when necessary.

Charger and Charging Procedure

MC6-WS is equipped with an internal rechargeable Lithium-ion (Li-ion) battery pack, which is charged when the CENTRiCAL bench is powered.

The battery charger is built into the CENTRiCAL Instrument Panel and is not intended for user service.

During charging, the battery icon and plug symbol alternate on the status bar. Once charging is complete, only the plug symbol is shown.

When MC6-WS is turned off but CENTRiCAL bench stays powered, the battery icon appears on the display.

After some time, the estimated charging time is shown below the battery icon.



Warning: Charge the battery pack only with the charger provided for MC6-WS (BC15). For more details on battery charging safety, see chapter [Warnings Concerning the Lithium-ion Battery Pack](#).

Power Management

To start the MC6-WS, switch the CENTRiCAL on and the MC6-WS will start automatically. To turn on only the MC6-WS, press and hold the **Calibrator Power** button for a few seconds.

The startup procedure ends in the **Home View**.



Figure 7: MC6-WS Calibrator Power button

Pressing the **Calibrator Power** button while the MC6-WS is running opens the Power Menu dialog with the following options:

- **Calibrator Power Off** — shuts down the Process Calibrator, using minimum battery power and requiring full startup on next power-on.
- **Standby** — puts the MC6-WS into Standby Mode, allowing faster startup when the **Power** button is pressed again.
- **Backlight Off** — temporarily turns off the display backlight



Note: To shut down the MC6-WS, follow these steps:

1. Switch the CENTRiCAL Mains switch off.
2. Press the MC6-WS **Calibrator Power** button.
3. Tap **Calibrator Power Off**.

Alternatively, if you need to use other devices mounted on the instrument panel:

1. Press the MC6-WS **Calibrator Power** button.
2. Tap **Standby** in the user interface. The MC6-WS enters Standby mode and remains in that state until the CENTRiCAL Mains switch is turned off.




Figure 8: Power Menu dialog

Pressing the **Tools** button () in the Power Menu window opens **Power Management** window, where you can adjust the Backlight Brightness and set auto-off delays for the backlight, display, and calibrator to save battery power.




Figure 9: Power Management window



Note: Auto-off feature is disabled in the following cases:

- Mains voltage is connected
- Adjusting MC6-WS own measurement, generation, or simulation ranges
- A data log is in progress
- An instrument calibration is in progress

User Interface

The MC6-WS offers several user interface modes optimized for different use cases.



Note: Some modes are optional and become available after enabling the software option.

Home View and User Interface Modes

Starting from the MC6-WS **Home View**, you can access any available user interface mode. This manual provides detailed information on the main user interface modes as follows:

- Meter
- Calibrator
- Documenting Calibrator
- Data Logger
- Communicator
- Settings




Figure 10: Home view



Tip: Use the **Home** button to quickly return to the Home View from anywhere.



Figure 11: Home button

Interacting with MC6-WS

You can interact with MC6-WS by tapping the available buttons and controls displayed on the touch screen. Alternatively, use the hardware **Arrow** buttons to navigate between buttons and controls. The first time you press a hardware **Arrow** button, the hardware focus indicator appears as a blue border around the active button or control. When navigating with the hardware Arrow buttons, press the hardware **Enter** button to confirm a selected button or control.



Figure 12: Button with and without hardware focus indicator

Buttons often open pop-up windows for entering data—for example, tapping a unit button labeled mmH₂O opens a pop-up window with available units. Some buttons have special functions, such as **Accept** and **Close** buttons, which close pop-up windows and either confirm or cancel changes. Other buttons allow you to move to the next or previous page or scroll through wide tables. **Back** button (←) can, for example, delete a number in a numeric field or clear a numeric field.



Figure 13: Accept button (left) and Close button (right)

The **Menu** button, located in the upper left corner of nearly every window, opens a context-sensitive menu.



Figure 14: Menu button




Figure 15: Open menu example

Check Boxes are a special type of button that can be either checked or unchecked.



Figure 16: Check boxes – checked (top) and unchecked (bottom)

MC6-WS also includes flat buttons, commonly used in lists. Their color may vary depending on the context. For example, to visually group calibration events, combined results belonging to the same event share the same shade of gray background. If an instrument's settings have changed, the related field displays a blue background.




Figure 17: Flat button list example

Editable Fields

The following editable fields are available:

- **Text fields**,
- **Numeric fields** (in certain cases including Spinning)
- **Date/Time fields**.

Text Fields

Letters and numbers in editable fields are shown in **blue** to indicate that they can be modified. **Black** text represents descriptive user interface labels that are not editable. An example of a text field and its edit window is shown in the images below.




Figure 18: Text field




Figure 19: Text edit window

Numeric Fields

Numeric fields are used when a generated, simulated, or other numerical value is either empty (displaying dashes) or when a new value is needed. To enter a value:

1. Tap the field to open the **soft numeric keypad**.




Figure 20: Soft numeric keypad

2. Use the keypad to enter the desired value.



Tip: Use the **Clear** button () to clear the entered value. The **Back** button () will delete the number to the left of the cursor.

3. Close the keypad by tapping **Accept** button — the entered value will then be applied.



Note: MC6-WS may use the entered value as a source for determining resolution. To ensure useful resolution, include trailing zeros where appropriate.

When applicable, **minimum and maximum limits** for the value are displayed above the numeric entry. If you enter a value outside these limits and attempt to accept it, MC6-WS will stay in the keypad window and replace your entry with the nearest acceptable limit, highlighting the replaced value.



Note: Because the MC6-WS uses floating-point numbers with six significant digits, rounding errors may occur in the seventh digit. When converting between binary and decimal values, exact matches may not always be found.



Tip: To input very small or large numbers into the **Factor** field, use the context-sensitive menu in the **Soft Numeric Keypad**. When available, this menu lets you insert an exponent and enter values in scientific notation, like 5.775E-07.




Figure 21: Context-sensitive menu in Factor window — Insert an Exponent

Spinning

Spinning is a tool available in **Calibrator** and **Documenting Calibrator** modes. It allows small, digit-by-digit adjustments to an existing numeric value.

Non-empty numeric fields in generation and simulation windows have a

Spinner button () to the left of the value. Tap the **Spinner** button to activate spinning.



Figure 22: Active spinner

When spinning is active, one digit will be highlighted. Use the **Up** and **Down** arrow buttons to increase or decrease its value. **Left** and **Right** arrow buttons will move the highlight to another digit.



Figure 23: Inactive spinner

To stop spinning, tap the **Spinner** button again.



Note: Changes made with the Spinner are applied immediately to the generated or simulated signal.

You cannot exceed the function's defined minimum and maximum limits.

The spun value follows the resolution rules of the function.

If the numeric field is empty (showing dashes), you must first enter a value using the soft numeric keypad before you can use the Spinning tool.

Date/Time Fields

Date and time fields work as a specific case of numeric fields. Entering a date is done in the same way as entering a numeric value using the soft numeric keypad.

Setting the time for MC6-WS is a special case of the Spinning functionality.




Figure 24: Time Setting window

Calibration Management Software

The MC6-WS communicates with Beamex CMX and LOGiCAL Calibration Management Software, supporting a fully digitalized calibration process.

The MC6-WS must be connected to a PC to communicate with the software. It operates with Microsoft's generic USB driver (WinUSB) and supports Windows® 11 operating system.

Communicating with LOGiCAL

MC6-WS communicates with LOGiCAL via the Beamex Sync application installed on a PC. Communication options include USB cable or wireless communication.

For wireless communication, a **Wireless Communication** option and Bluetooth adapter are required. More details are provided in chapter [Wireless Communication](#).

For instructions on syncing data between MC6-WS and LOGiCAL using Beamex Sync, refer to the [LOGiCAL Help](#).

Communicating with CMX

MC6-WS is compatible with CMX version 2.7 and later.

The MC6-WS can establish direct communication with a PC with CMX installed, using either a USB connection or Bluetooth.

For Bluetooth communication, a wireless option and Bluetooth adapter are required. More details are provided in chapter [Wireless Communication](#).

In addition to local connections, MC6-WS can communicate with CMX over Wide Area Networks via the Calibration Web Service Interface (CWSI).

Customers may either implement a local CWSI environment or use Connect.beamex.com, a secure web service hosted by Beamex.

For more details about transferring data between MC6-WS and CMX, refer to the *CMX User Manual*.

Options, Accessories and Services

To support your changing needs, Beamex regularly releases firmware updates that add features and enhance performance. You can also upgrade your

calibrator with additional hardware modules or software options. Accessories are available in the [Beamex Webshop](#). For further details, contact Beamex.

Software Options

The following software options are available:

- **Communicator options for HART, FOUNDATION Fieldbus H1, or Profibus PA** allow the calibrator to function as a fieldbus communicator. All three options can be installed in the same unit. The Communicator user interface mode is activated when any of these protocols are installed.



Note: Fieldbus hardware capability must be installed with FOUNDATION Fieldbus and Profibus PA Communicator options. You can verify if the communication hardware required for fieldbus communication is installed on the first page of the **Settings > About** window.

- **Data Logger** allows logging of various measurement results. The Data Logger user interface mode is activated only if this option is installed.
- **Communication drivers** are available for external pressure controllers and temperature dryblocks, enabling fully automatic calibration of various pressure and temperature instruments.
- **Wireless Communication** functionality supports wireless transfer of instrument and calibration data between MC6-WS and Beamex Calibration Management Software.



Note: Bluetooth is an alternative data transfer method between the calibrator and PC. USB cable connection is also supported.

- **Mobile Security Plus** technology ensures calibration data integrity during calibrations. This option works only with CMX Calibration Management Software, version 2.11 or later, and when the Mobile Security Plus option is installed in CMX and the MC6 family calibrator.



Note: The software options installed in your MC6-WS can be viewed on the third page of the **Settings > About** window.



Note: You can purchase additional software options for your existing calibrator. After purchase, Beamex provides you with an option file (.opt). The option file is installed on the calibrator using the **MC6 Option Installer** PC tool. To purchase options, please contact Beamex Sales.

Accessories and Related Products

You can use the MC6-WS together with a wide selection of complementary products, including Beamex ePG Electric Pressure Pump and Controller, RPRT, IPRT, and SIRT temperature sensors, EXT External Pressure Modules, and calibration pumps for different pressure ranges. Visit the [Beamex website](#) for more details.

Accessories are available in the [Beamex Webshop](#).

Services

Like any precision instrument, calibrators require regular calibration to maintain accuracy and meet compliance requirements. Keeping your calibrator up to date with scheduled recalibrations ensures reliable performance and extends its service life.

Beamex provides calibration services, repairs, and service plans to support the long-term performance of your equipment.

For details, visit the [Beamex website](#).

Available PC Tools

A selection of PC tools is available under the Resources tab on the [MC6-WS page](#) on the Beamex website. Available tools include:

- **Data Log Viewer** – transfer and view logged data from the calibrator on your PC. See chapter [Data Log Viewer](#) for details.
- **Option Installer** – install optional features on your calibrator. After purchasing a software option for an existing calibrator, Beamex creates and delivers an option file (.opt) to you.
- **Remote Controller** – control the calibrator from a PC, which is particularly useful for training purposes and capturing user interface screenshots.
- **Device Description Installer** – transfer updated Device Descriptions from your PC to the calibrator. More details can be found in chapter [Device Description Files](#).
- **Fieldbus Configuration Viewer** – view and manage smart instrument configurations. Additional information is available in chapter [Managing Smart Instrument Configurations in MC6-WS](#).

Calibration Capabilities and Connections

The MC6-WS is a high-accuracy, multifunction calibrator designed for calibrating pressure, temperature, and a variety of electrical signals. This section of the user manual describes all the measurement, generation, and simulation functions the MC6-WS can perform.

Each diagram shows which connectors and terminals to use for each function, along with the required connection cables and any optional connections.



Tip: The connection diagrams are also available in the Documenting Calibrator user interface mode to help make the required connections for the selected measurement, generation, or simulation function.




Figure 25: Connection diagram example

Legend:

1. Active terminals
2. Terminal not to be used

3. Possible optional connections
4. Connection cables

For information about using external controllers like pressure controllers and temperature dry blocks in Calibrator and Documenting Calibrator modes, see chapter [Controller Communication](#).

Measurements

Pressure Measurement

MC6-WS works with pressure modules in CENTRiCAL (if installed) and supported panel-mounted **EXT** CENTRiCAL or portable **EXT**, when connected to the **PX** connector.

You can find the available pressure module types and their measurement ranges in chapter [Pressure Modules](#).



Warning: Always choose a pressure module with a measurement range appropriate for your pressure signal. Using a module outside its intended range can cause inaccurate results, damage to the module, or safety risks.



Caution: Accurate pressure measurement requires understanding the different **pressure types**: absolute, gauge, and differential. Measuring pressure without adequate knowledge of these types or the hazards of pressure devices can lead to incorrect measurement results and potentially serious accidents.

Please refer to the warnings in chapter [Warnings Concerning Pressure](#).




Figure 26: Pressure module connectors example




Figure 27: PX connector for external pressure measurement module in MC6-WS



Note: The number of pressure modules in CENTRiCAL in your MC6-WS may not match the illustration shown above.

Before starting pressure measurements, check these settings:

- **Pressure Type** — lets you select the appropriate type based on your measurement setup.
- **Zeroing** — allows you to set the pressure module reading to zero.



Figure 28: Pressure measurement buttons



Note: If a selected pressure module does not display zero when no pressure is applied, it must be zeroed. To zero a pressure module, ensure zero gauge pressure is applied, then press the **Zero** button






Figure 29: Pressure Type window

User-Defined Pressure Units

When pressure is selected as the **Quantity**, you can choose from a wide range of pressure units organized across multiple pages. Additionally, you can add your own custom pressure units to the following page(s)

To create a new custom unit, go to the **Configuration** page, press **Create New** button (📄), and give the unit a clear, descriptive name.





Figure 30: User Units window — Create New button for user-defined pressure units

Next, select a **Reference Unit** and enter the **Factor**, which defines the relationship between your new unit and the reference unit. The **Reference Unit** can be any of the predefined pressure units available in MC6-WS.



The image shows a 'User Unit' configuration window. It has a title bar with a home icon, a menu icon, and a close button (X). The window contains the following fields:

- User Unit Name:** A text box containing 'Tons (US) / ft²'.
- Factor:** A text box containing '1.04272'.
- Reference Unit:** A button labeled 'bar'.
- Notes:** A large empty text area.

There is a green checkmark button in the bottom right corner.

Figure 31: User-defined pressure unit configuration window

Whenever a custom unit is in use, a warning symbol (Δ) appears next to the unit's name, as shown in the example below. together with the name of the user defined pressure unit, as shown in the example below.




Figure 32: User-defined pressure unit example in Calibrator

Other user interface modes display the custom unit in a similar way.



Note: To select **pressure** as a **Quantity**, make sure you have either an internal barometric module or an external pressure module connected to MC6-WS.

Connecting and Disconnecting External Pressure Modules

All Beamex EXT external pressure modules use a 4-pin LEMO connector compatible with the PX connector.

When you connect an external pressure measurement module, MC6-WS opens a dialog where you can review information and select where to use the connected module.

You can disconnect an external pressure module whenever needed. MC6-WS will notify you when a module has been removed, and if it was active in a measurement, that measurement will stop.



Note: When using MC6-WS with an EXT module together with CMX or LOGiCAL, keep the module connected to the calibrator while communicating with the software. This ensures that, if the module has been recalibrated, its calibration date is automatically updated in the CMX/LOGiCAL reference database.

Temperature Measurement (RTD)




Figure 33: RTD temperature measurement terminals

MC6-WS supports a range of standard Platinum Resistance Temperature (PRT) RTD sensors, available when RTD Temperature is selected as the Quantity. Always confirm the sensor type on your connected device and set the same type in your MC6-WS unit. Incorrect settings will lead to inaccurate measurements. The available measurement range depends on the selected sensor type.

For R1 terminals:

For 2-wire measurements, use the two lowest terminals. MC6-WS automatically detects and displays the wiring configuration (2-wire, 3-wire, or 4-wire) when a connection is made.



Note: For 3-wire systems, use the terminal marked "3W".

For R2 connector: All Beamex temperature sensors use a 6-pin LEMO connector compatible with the R2 connector. If you need to connect a non-Beamex Pt-sensor, suitable adapter cables can be found in the [Beamex Webshop](#).




Figure 34: Female connector (R2) in MC6-WS

R2 connector pin layout:

1. Excitation current +
2. Sense +
3. 1-Wire Ground
4. Sense -
5. Excitation current -
6. 1-Wire IO
7. Not used

See also chapters:

- [RTD Simulation](#)
- [Resistance Measurement](#)
- [Resistance Simulation](#)



Tip: To ensure proper contact between the test leads and the device under test, we recommend using the supplied alligator clips.



Note: If you encounter a “+OVER” or “-OVER” error, check your connections. You can also use the 2-wire resistance measurement function to verify the wiring.

Temperature Measurement (Thermocouple)

MC6-WS has two thermocouple ports: **TC1** for standard thermocouple plugs and cables, and **TC2** for plugs with flat contacts.




Figure 35: Thermocouple temperature measurement terminals

Before starting measurements, confirm the sensor type of your connected device and select the corresponding thermocouple type in your MC6-WS. Choosing the wrong type will result in unreliable data. The available measurement range depends on the sensor type. Make sure to also select an appropriate **Reference Junction** compensation method. Incorrect settings will result in invalid measurement results.

See also chapters:

- [Thermocouple Simulation](#)
- [Voltage Measurement](#)



Warning: When using another thermocouple or an RTD connected to MC6-WS to measure the external reference junction temperature, remember that there is no galvanic isolation between the connected devices.



Note: Thermocouple measurements can be sensitive to errors caused by poor connections, incorrect extension cables, or wrong settings in MC6-WS. If you're uncertain about your setup, see chapter [Thermocouple Connections](#) and consult thermocouple reference materials.

Resistance Measurement

Measurement range: **-1 ... 4040 Ω**




Figure 36: Resistance measurement terminals

For R1 terminals:

For 2-wire measurements, use the two lowest terminals. MC6-WS automatically detects and displays the wiring configuration (2-wire, 3-wire, or 4-wire) when a connection is made.



Note: For 3-wire systems, use the terminal marked "3W".

For R2 connector: All Beamex temperature sensors use a 6-pin LEMO connector compatible with the R2 terminal. If you need to connect a non-Beamex Pt-sensor, suitable adapter cables can be found in the [Beamex Webshop](#).

See also chapters:

- [Resistance Simulation](#)
- [Temperature Measurement \(RTD\)](#)



Note: To ensure proper contact between the test leads and the device under test, we recommend using the supplied alligator clips.



Note: If you encounter a "+OVER" or "-OVER" error, check your connections. You can also use the 2-wire resistance measurement function to verify the wiring.

Current Measurement

Measurement range (internal supply): **-101 ... 101 mA DC**

When measuring electric current, you need to decide whether MC6-WS will supply the **24 V loop supply voltage**. If it does not, an external device must be used to provide the loop supply voltage.

The connection depends on the selected loop supply setting.




Figure 37: Current measurement terminals, internal supply




Figure 38: Current measurement terminals, external supply

See also chapter:

- [Current Generation \(Source or Sink\)](#)

Voltage Measurement

The voltage measurement ports available on MC6-WS, along with their ranges, are listed below:

- **TC1** Measurement range: -1.01 ... 1.01 V DC
- **TC2** Measurement range: -1.01 ... 1.01 V DC
- **IN** Measurement range: -1.01 ... 60.6 V DC




Figure 39: Voltage measurement terminals



Note: Non-supported thermocouple signals can be measured with MC6-WS using the TC1 or TC2 ports. The result will be shown in millivolts (mV), and you'll need a reference table to convert those values into temperatures.



Tip: The **Scaling** function, available in Calibrator user interface mode, makes it possible to convert millivolt readings into temperatures.



Warning: Never apply hazardous voltages (over 30 V AC or 60 V DC) to the MC6-WS terminals.

See also chapters:

- [Voltage Generation](#)
- [Temperature Measurement \(Thermocouple\)](#)

Frequency Measurement

Measurement range: **0.0027 ... 51 000 Hz**




Figure 40: Frequency measurement terminals

When measuring frequency, be sure to select an appropriate **Trigger Level** setting. You can access the settings by pressing the Trigger Level button.



Figure 41: Trigger Level button

There are separate trigger level options for dry and wet contacts:

- **Dry Contact** — typically, the signal comes from a mechanical switch. MC6 supplies 3 V and sets the trigger level to 1 V, allowing it to detect the state of the contact.
- **Wet Contact** — the signal has its own internal voltage supply. You only need to set the trigger level voltage in the calibrator to detect the signal state. The value can also be manually adjusted using the **Manual Trigger Level (V)** flat button.




Figure 42: Trigger Level window

See also chapters:

- [Frequency Generation](#)
- [Pulse Counting](#)
- [Switch Sensing](#)

Pulse Counting

Measurement range: **0 ... 9,999,999 pulses**




Figure 43: Pulse counting terminals

Before you start or restart a pulse count, make sure to check the following settings:

- **Trigger Level** — choose a level appropriate for your signal. For details, see chapter [Frequency Measurement](#).
- **Trigger Edge** — set to either rising or falling edge, depending on your needs.
- **Zeroing** — use this to reset the pulse count to zero if needed.



Figure 44: Trigger Level, Trigger Edge, and Zeroing buttons




Figure 45: Trigger Edge window

See also chapters:

- [Pulse Generation](#)
- [Frequency Generation](#)
- [Frequency Measurement](#)

Switch Sensing




Figure 46: Switch sensing terminals

Make sure to check the following switch sensing settings:

- **IN: Normal** — allows you to reverse the open/close indication of the switch.
- **Trigger Level** — choose a trigger level suitable for your switch.
- **Switch Sound** — decide whether MC6-WS plays a sound when the switch changes state, and define which event triggers it.



Figure 47: Trigger Level and Switch Sound buttons




Figure 48: Switch Sound window

See also chapters:

- [Pulse Counting](#)

- Pulse Generation



Tip: Switch sensing can also detect binary signals.

By default, an open switch equals **1 / True** — and a closed switch equals **0 / False**.



Tip: For switches without an electrical contact, use the Manual Trigger by pressing the **Switch** button () during calibration.

Electrical Generations and Simulations

Generations and simulations are supported in **Calibrator**, **Documenting Calibrator**, and **Data Logger** user interface modes.



Note: The **Meter** mode cannot perform generations or simulations.

RTD Simulation

RTD simulation is available only from the R1 terminals.




Figure 49: RTD simulation terminals

The receiving instrument determines whether a 2-, 3-, or 4-wire connection is used. Connect any additional third and fourth wires as required but always **use only the two lowest R1 terminals** in MC6-WS.

Always confirm the sensor type on your connected device and set the same type in your MC6-WS unit. Incorrect settings will lead to inaccurate measurements. The available measurement range depends on the selected sensor type.

See also chapters:

- [Temperature Measurement \(RTD\)](#)
- [Resistance Simulation](#)



Warning: Keep in mind that RTD simulation accuracy can be affected if the connected transmitter uses a test pulse function that cannot be disabled.



Tip: To ensure proper contact between the test leads and the device under test, we recommend using the supplied alligator clips.



Note: AC measurement current from the device under test is not supported. If the device under test uses pulsed measurement current, include a delay of a few milliseconds before measuring resistance.

Thermocouple Simulation

Thermocouple simulation is available only from the TC1 terminals.




Figure 50: Thermocouple simulation terminals

Always confirm the sensor type on your connected device and set the same type in your MC6-WS unit. Incorrect settings will lead to inaccurate measurements. The available measurement range depends on the selected sensor type. Make sure to also select an appropriate **Reference Junction** compensation method. Incorrect settings will result in invalid measurement results.

For more information on thermocouple connections and reference junction setting, see chapter [Thermocouple Connections](#).

See also chapter:

- [Temperature Measurement \(Thermocouple\)](#)



Warning: Keep in mind that thermocouple simulation accuracy can be affected if the connected transmitter uses a test pulse function that cannot be disabled.



Warning: When using another thermocouple or an RTD connected to MC6-WS to measure the external reference junction temperature, remember that there is no galvanic isolation between the connected devices.



Note: Thermocouple measurements can be sensitive to errors caused by poor connections, incorrect extension cables, or wrong settings in MC6-WS. If you're uncertain about your setup, see chapter [Thermocouple Connections](#) and consult thermocouple reference materials.

Resistance Simulation

Resistance simulation is available only from R1 terminals.

Simulation range: **0 ... 4000 Ω**




Figure 51: Resistance simulation terminals

The receiving instrument determines whether a 2-, 3-, or 4-wire connection is used. Connect any additional third and fourth wires as required but always **use only the two lowest R1 terminals** in MC6-WS.

MC6-WS monitors the resistance measurement current. If the current rises too high, MC6-WS cannot simulate the desired resistance value and will display an error message.

See also chapters:

- [Resistance Measurement](#)
- [RTD Simulation](#)



Warning: Keep in mind that resistance simulation accuracy can be affected if the connected transmitter uses a test pulse function that cannot be disabled.



Note: When you simulate the resistance or an RTD sensor using R1 terminals, MC6-WS does not support measuring the simulated signal using R2 terminals.



Tip: To ensure proper contact between the test leads and the device under test, we recommend using the supplied alligator clips.



Warning: AC measurement current from the device under test is not supported. If the device under test uses pulsed measurement current, include a delay of a few milliseconds before measuring resistance.

Current Generation (Source or Sink)

Generation range (internal supply): **0 ... 55 mA DC**

You can generate current with MC6-WS using one of two methods:

- MC6-WS provides a loop supply voltage (source mode).

Setting: **Supply: On.**

- An external device provides the loop supply voltage (sink mode)

Setting: **Supply: Off.**

Connection depends on the loop supply setting.




Figure 52: Current generation terminals, internal supply




Figure 53: Current generation terminals, external supply

See also chapter:

- [Current Measurement](#)



Warning: Do not exceed the maximum current allowed by the device under test.

If the loop is opened during current generation, MC6-WS attempts to maintain the current by increasing its output voltage. When the loop is closed again, a short current peak may occur before stabilizing. To avoid potential damage from this peak, ensure the loop cannot open during operation, or use overcurrent protection. Always set the output to 0 mA before connecting the loop.



Note: If MC6-WS is supplying 24 V and you connect a smart instrument, the battery symbol (🔋) appears in the Documenting Calibrator and Data Logger user interface modes.

Voltage Generation

The voltage generation terminals of MC6-WS and their corresponding generation ranges are shown below:

- **TC1** Generation range: -1 ... 1 V DC
- **OUT** Generation range: -3 ... 24 V DC




Figure 54: Voltage generation terminals

See also chapters:

- [Voltage Measurement](#)
- [Thermocouple Simulation](#)



Warning: Starting the voltage generation mode causes a short 24 V voltage peak. To prevent damage, connect the terminals only after entering voltage generation mode.

Always set the output to 0 V before making the connection.



Warning: If the voltage output is short-circuited, it can damage both the calibrator and the connected instrument.

Frequency Generation

Generation range: **0.0005 ... 50 000 Hz**




Figure 55: Frequency generation terminals

Before generating a frequency signal, check the following settings:

- **Amplitude** — define the desired voltage using the '**value**' V flat button.
- **Waveform & Duty Cycle** — choose either a Positive or Symmetric waveform and set the Duty Cycle.



Figure 56: Amplitude and Waveform & Duty Cycle buttons

The Duty Cycle defines the proportion of high output time relative to the total cycle. At higher frequencies, technical limitations may prevent the calibrator from achieving the exact Duty Cycle you set. In such cases, an asterisk (*) appears before the displayed Duty Cycle to indicate the difference.




Figure 57: Waveform & Duty Cycle window

See also chapters:

- [Frequency Measurement](#)
- [Pulse Generation](#)

Pulse Generation

Generation range: **0 ... 9,999,999 pulses**




Figure 58: Pulse generation terminals

Before starting pulse generation, check the following settings:

- **Frequency** – specify the frequency by pressing the '**value**' Hz flat button.
- **Amplitude** — define the desired voltage using the '**value**' V flat button.
- **Waveform & Duty Cycle** — choose either a Positive or Symmetric waveform and set the Duty Cycle.



Figure 59: Frequency, Amplitude, and Waveform & Duty Cycle buttons

The Duty Cycle defines the proportion of high output time relative to the total cycle. At higher frequencies, technical limitations may prevent the calibrator from achieving the exact Duty Cycle you set. In such cases, an asterisk (*) appears before the displayed Duty Cycle to indicate the difference.

See also chapters:

- [Pulse Counting](#)
- [Frequency Generation](#)

Smart Instrument Connections

When working with smart instruments, it is important to choose the suitable power supply and ensure proper connections. Incorrect settings can lead to invalid measurement results. Choose the power supply source from the following options:

- **Internal power supply**

The MC6-WS internal power supply can safely power a single instrument. If your HART or fieldbus segment includes multiple instruments, consider using an external power supply.




Figure 60: Smart instrument terminals, internal supply

- **External power supply**

To maintain communication, you might need an external resistor—250 Ω for HART or 50 Ω for fieldbus. If you use a fieldbus-compliant power supply, an external resistor is not necessary.




Figure 61: Smart instrument terminals, external supply



Note: You can connect MC6-WS to the instrument or fieldbus using standard measurement cables. For longer cable runs, fieldbus terminators might be required.



Warning: PROFIBUS PA segment: Never connect two master devices (such as MC6-WS, a field communicator, or a control system) simultaneously to the same segment. Doing so can cause conflicts and make the segment unstable. Always remove the instrument to be calibrated from the live segment before calibration.

See also chapter [Warnings Concerning Smart Instruments](#).

Further details about smart instruments are available in chapter [Working With Smart Instruments](#).

Thermocouple Connections

When working with thermocouples, it is important to choose the suitable **Reference Junction** compensation method and ensure proper connections. Incorrect settings can lead to invalid measurement results. Choose the Reference Junction mode from the following options:

- **Internal**

Connect the MC6-WS using appropriate thermocouple, extension, or compensation wires. The calibrator automatically manages the reference junction compensation. If needed, you can also use the TC2 terminal.




Figure 62: Internal Reference Junction

- **External R1 and External R2**

Connect an external RTD sensor to the selected terminal to measure the Reference Junction temperature. You may optionally also use the TC2 terminal.




Figure 63: RTD connected to R1 terminals measuring the Reference Junction temperature

- **Fixed (0°C) and Manual**

Use this option when the reference junction temperature is controlled by a compensation box, temperature controller, or other similar method. **Manual** mode lets you enter any temperature, while **Fixed (0 °C)** mode provides a shortcut for setting 0 °C. You may optionally also use the TC2 terminal.

Meter

The **Meter** user interface mode allows you to measure any signal supported by the MC6-WS, one signal at a time.

To start the Meter mode, tap the **Meter** button in the Home view.




Figure 65: Home view, Meter user interface mode

To measure the signal:

1. Select the **Quantity** of the signal from the lower section of the Meter window.
2. Configure quantity-specific settings in the top section.




Figure 66: Current measurement in Meter

The button on the left opens the Port/Function selection and displays the measuring range for each port of the selected quantity. Connection diagrams help with the required connections. The purpose of the other buttons varies depending on the quantity; for example, in TC measurement you can select the sensor type. The unit button next to the measured signal lets you change the unit.

For details on connections and quantity-specific settings, see chapter [Calibration Capabilities and Connections](#).

Calibrator

The **Calibrator** user interface mode is designed for calibrating instruments. It allows you to independently configure two signals—for example, one as the instrument's input and the other as its output—to be measured, generated, or simulated.

To start the Calibrator mode, tap the **Calibrator** button in the Home view.




Figure 67: Home view, Calibrator user interface mode

To configure the signal:

1. Choose the **Quantity** of the signal for both input and output.
2. Use Port/Function to select whether to **measure**, **generate**, or **simulate** the signal, and follow the connection diagrams to make the necessary connections.
3. Configure the quantity-specific settings.




Figure 68: Calibrator configuration window



Tip: Tapping the **Tools** button () opens a menu showing the available tools. Certain tools are limited to use with measurements or generations. A complete list can be found in the [Tools](#) section.

For details on connections and quantity-specific settings, see chapter [Calibration Capabilities and Connections](#).



Note: If one signal is set to generate and the other to switch sensing, the switch captures the generated value when it actuates. This enables manual calibration of switches. However, for temperature switches, always use **Documenting Calibrator** mode for accurate calibration.



Note: To document calibration data automatically, use the Documenting Calibrator mode.



Note: For information about using external controllers like pressure controllers and temperature dry blocks in Calibrator mode, refer to chapter [Controller Communication](#).

Documenting Calibrator

The **Documenting Calibrator** mode is designed for documented and automated calibration of process instruments. In this mode, the calibration process is guided, and the calibrator can automatically set the calibration points and record the results. The Documenting Calibrator mode works with Beamex Calibration Management Software.



Note: The calibrator automatically synchronizes its date and time with the computer during communication with the calibration management software, ensuring correct time settings.

To start the Documenting Calibrator mode, tap the **Documenting Calibrator** button in the Home view.




Figure 69: Home view, Documenting Calibrator user interface mode

Calibration Process with MC6-WS

Calibration is a documented comparison of a measurement device to be calibrated against a traceable reference.

When calibrating instruments, a calibration reference with a known value must be compared to the instrument's measurement value. The calibration process must be documented, and comparison calculations performed.

A documenting multifunction calibrator performs all these tasks and can even carry out fully automatic calibrations.

The MC6-WS is a documenting calibrator that communicates with Beamex LOGiCAL or CMX Calibration Management Software, enabling a fully digitalized calibration process.

Instrument Data

The **Instrument data** in MC6-WS includes all the necessary components to define how a calibration process should be carried out. It is recommended to use calibration management software to determine what to calibrate, how, and when. When the instrument is due for calibration, its data can be transferred from the Calibration Management Software to the calibrator. You can also create and save instrument data directly in the Documenting Calibrator. With smart instruments, some data elements can also be populated directly from the instrument.

The **Identification** data describes the instrument to be calibrated. **Device** can be defined as the physical product (asset) performing the process measurement. **Position** specifies the functional location in the process the device is installed (commonly called the Tag). Defining the position is optional, but allows you to define a hierarchical Plant Structure where the position can be placed. The Plant Structure is typically maintained in the Calibration Management Software.

In calibration, **Input** (the calibration reference with a known value) is compared to the instrument's **Output**. MC6-WS can provide the input signal and measure the output signal for pressure, temperature and various electrical signals. You can also manually enter the input or output signal into the calibrator (Keyed) if necessary.

The **Function** describes the measurement capability of the instrument to be calibrated. Function is described by its quantity, unit, range, and sensor type.



Note: Measurement devices like sensors and switches usually handle one quantity and range.

Industrial transmitters measure a physical quantity (such as pressure or temperature) and convert it into an electrical or digital signal using a transfer function. In these cases, the input and output quantities and ranges are different.



Note: Be sure to define the quantity, unit, and range for both input and output—even when the values are the same.



Tip: When the input signal is pressure or temperature, the Automatic Control feature can assign a supported external controller to generate the reference pressure or temperature automatically. The calibrator can also simulate temperature if needed.

Calibration is performed according to the **calibration procedure**. By default, calibration point values are distributed evenly across the instrument range. You can set the calibration direction as up, down, down-up, or up-down. If the standard configurations are not suitable, you can also define fully customized calibration points. You can enable Automatic Acceptance of calibration points if certain conditions are met (see chapter [Calibration Point Acceptance](#) for details).

The **Error Limit** defines the maximum acceptable calibration error. Error is calculated as the difference between the input and output signals—i.e., the reference value and the measured value of the instrument to be calibrated.



Note: For transmitters, the error is the difference between the expected (ideal) output signal—calculated using the transfer function—and the actual measured output signal.

Calibration passes only if measured error in all calibration points are within the defined limit. Otherwise the calibration fails.

Calibration Execution and Calibration Results

After the instrument data has been created in the Documenting Calibrator or received from the Calibration Management Software, the instrument is ready for calibration.

The Documenting Calibrator walks you through the calibration process step by step, progressing through the defined calibration points. Depending on the defined procedure, points can be accepted manually or automatically.

Documenting Calibrator captures the data digitally and automatically documents the calibration. Once completed, a result preview is displayed, with both numerical and graphical views available. The calibrator calculates the

measurement error and performs a pass/fail check based on the measured input/output values and the defined error limits. The pass/fail result is the key outcome of the calibration. The first calibration repeat can be saved as the **As Found** calibration.

If the calibration fails or the error is too close to the defined limit, you can adjust the instrument.



Tip: MC6-WS can perform adjustments for smart instruments. For more information, see chapter [Trimming Smart Instruments](#).

After adjustment, you can perform a new calibration repeat—called **As Left**—to document the instrument's post-adjustment condition. If the instrument cannot be adjusted to meet the calibration requirements, consider replacing it with a more accurate one.

Once the calibration is complete, it is recommended to transfer the results to Calibration Management Software to maintain a complete calibration history. The calibration data stored in the Calibration Management Software is easily available for analysis, reporting, and creating calibration certificates.



Note: Calibration results can be temporarily stored in the calibrator's memory, but for permanent storage, it is strongly recommended to use Calibration Management Software.

Instrument List

When you start the Documenting Calibrator, the Instrument List window opens if there are instruments saved in the calibrator.

Tap an instrument to select it for calibration. This opens the Instrument Overview window, which shows general information about the selected instrument. For more details on the Instrument Overview window, refer to chapter [Instrument Overview Window](#).

It is recommended to use calibration management software to manage instruments and transfer the data to the calibrator when the instrument is due for calibration. You can also create and save instruments directly in the Documenting Calibrator. For instructions, see chapter [Creating Instruments in MC6-WS](#).




Figure 70: Instrument List example

Legend:

1. Instruments listed at the current Plant Structure Level.
2. Sublevel within the Plant Structure. A detailed description is available in chapter [Plant Structure Levels](#).
3. Menu for managing the Instrument List. More information in chapter [Instrument List Menu](#).
4. Total number of instruments at this level and all sublevels.
5. Name of the current Plant Structure Level.
6. Sorting order icon. Refer to chapter [Instrument List Menu](#).
7. **Return** button () to move one level up in the Plant Structure.
8. **Create New** instrument button (). Detailed instructions for creating instruments are provided in the chapter [Creating Instruments in MC6-WS](#).
9. Page navigation buttons for browsing a multi-page Instrument List.




Figure 71: Instruments in the Instrument List

Legend:

A. Function Name.

B. Position ID.



Note: When Position information is not available, the Device ID is displayed instead.

C. Most recent calibration result: "Passed" (visible only if the instrument has been calibrated).

D. Calibration Due Date.

E. Most recent calibration result: "Failed" (visible only if the instrument has been calibrated).



Note: You can also view instruments in Work Order View Mode. More information in chapter [Work Order View Mode](#).

Plant Structure Levels

Tap a Plant Structure Level to display its sublevels and the instruments it contains. To move one level up in the hierarchy, tap the **Return** button ().




Figure 72: Plant Structure Level in the Instrument List

Legend:

1. Sublevel within the Plant Structure.
2. Total number of instruments at this level and all sublevels.
3. Title bar active area – tap to display the full Plant Structure path.
4. Name of the current Plant Structure Level.
5. Number of sublevels and instruments within them.



Note: For details on how to create and manage Plant Structure Levels, see chapter [Instrument List Menu](#).

Instrument List Menu

Tap the Instrument List context-sensitive menu (3 in [Figure 70: Instrument List example](#)) to access additional tools for managing the Plant Structure and Instrument List.




Figure 73: Instrument List menu

Create New – allows you to create new items:

- Instrument – creates a new instrument (see chapter [Creating Instruments in MC6-WS](#) for instructions).
- Plant Structure Level – adds a new sublevel to the current level.
- Group – creates a new calibration group (see chapter [Group Calibration](#) for more details).

Sort – let you organize list content by:

- Instrument Identification – alphabetically, Ascending () or Descending ().
- Due Date – Ascending () or Descending ().
- Creation – Ascending () or Descending ().

Show – filter () the list view to show:

- All – all instruments and levels.
- Calibrated – only calibrated instruments.
- Not Calibrated – only not calibrated instruments.
- Not Calibrated and Failed – instruments that are either not calibrated or have failed calibration.

View Mode – control how the Plant Structure is displayed:

- Obey Structure
- Ignore & Hide Structure
- Show All from Here/Below
- Show Instruments from Here/Below

- Work Order (see chapter [Work Order View Mode](#))

Browse – allows you to search () for instruments or jump to the beginning or end of the list.

Manage – delete instruments or results, or manage the Plant Structure.



Caution: Deleting a Plant Structure Level will also delete all instruments and calibrations on that level and below. The root level cannot be deleted.



Warning: Deleted items cannot be recovered.

Instrument Overview Window

Selecting an instrument for calibration opens the Instrument Overview window. This window presents general details of the instrument configuration data and provides connection diagrams for the selected input and output functions. The diagrams show which connectors and terminals to use for attaching the test leads, helping you make the correct connections. For further details on connections and required communication cables, see [Calibration Capabilities and Connections](#).



Note: If available, a Before Calibration Note will be displayed.



Tip: Before beginning calibration in the Documenting Calibrator, you can use Calibrator mode to verify that the test leads are connected properly and that input and output signals can be provided.




Figure 74: Instrument Overview window

From the Instrument Overview window, you can:

- Return to the Instrument List by tapping **Close** button (✖).
- Edit or review instrument configuration data by pressing **Configure** button (⚙). For a detailed description of all instrument data pages, see [Creating Instruments in MC6-WS](#).
- View existing calibration results by tapping the **View Results** button (📄).
- Start calibrating the selected instrument and open the Calibration window by pressing the **Accept** button (✅).

The context-sensitive menu provides options to Copy, Move, or Delete the selected instrument, as well as view the Plant Structure.

Calibrating an Instrument

After selecting the instrument to be calibrated, check the displayed connection diagram to see where to connect the leads.



Note: Use the **Info** button (📘) to view connection diagrams.

Once connected, tap the **Accept** button (✅) in the Instrument Overview window (see [Figure 74: Instrument Overview window](#)). The **Calibration** window opens, displaying the nominal input and output values for the first calibration point.



Note: To perform smart instrument calibration, check the instructions in chapter [Calibrating Smart Instruments](#).




Figure 75: Calibration window



Note: If gauge pressure modules are used, zero them before beginning calibration.

Tap the **Start** button to begin the calibration.



Note: Generations are started in the Instrument Overview window before the **Start** button is pressed.

If **Automatic Acceptance** is enabled, calibration points will be accepted automatically. Otherwise, you must manually accept each point. See section [Calibration Point Acceptance](#) for more on accepting calibration points.



Note: Tap the **Back** button to return to the Instrument Overview window.




Figure 76: Calibration with manual acceptance

As calibration progresses, each accepted point appears on the graph—passed points in green, failed points in red. Points are linked with a thin line to indicate the point sequence. A grey column marks the next target point, and its width is determined by the **Max. Point Deviation** setting. The numeric value of the next target point is shown in the lower-right corner. If any point exceeds the defined error limits (blue dotted lines), the line turns red.

Use the **Pause** button (⏸) to reject a calibration or undo a point. The **Notes** button (💬) lets you add notes to individual calibration points. Additional settings are available in the context-sensitive menu.

Various tools are available under the **Instrument Input/Instrument Output** menu items in the Calibration window. Tap the **Tools** button (🔧) to view the available tools. The tool selection depends on the selected Quantity and Port. These tools are also available during instrument configuration. For details, see chapter [Tools](#).



Note: Certain tools are not compatible with the Calibration Management Software.

Calibration Point Acceptance

Calibration points can be accepted either manually or using Automatic Acceptance feature. When **Automatic Acceptance** is not in use, you must manually accept each calibration point using the **Accept Point** button when signals are stable. The MC6-WS then proceeds to the next calibration point.



Note: Use the **Force Accept** button to manually accept points when, e.g. the calibration does not advance because of an unstable input and/or output signal or the input point is not within the maximum deviation window.

The following instrument data should be defined when using the **Automatic Acceptance** feature:

- Max. Point Deviation (% of span) – the acceptable deviation of the input signal from the nominal value.
- Stability – of both input and output signals.
- Point Delay – the time (in seconds) the calibrator waits before accepting the values.

When **Automatic Acceptance** is enabled (checked), MC6-WS accepts calibration points automatically, following this process:

1. MC6-WS checks whether the input signal falls within the Max. Point Deviation value of the next calibration point.
2. When the input signal is close enough, MC6-WS checks the signal stability to decide whether the readings can be saved.
3. When signal stability is reached, a timer (⌚) counts down the **Point Delay** amount of seconds. After that, the readings are saved only if the signal is still stable. If the signal becomes unstable, MC6-WS returns to step two.




Figure 77: Calibration with Automatic Acceptance in use



Note: Opening the menu during calibration pauses the process until the menu is closed.

Calibration Results Window

After the calibration is completed, the Calibration Results window opens and indicates whether the calibration **Passed** or **Failed**. The results are shown on multiple pages, offering different views of the calibration data, such as numerical values, graphical representation, and general information.



Note: The number of result pages shown in the Calibration Results window can be adjusted through the menu. To view only the basic result pages, select **Show, Basic Pages**. To include all available pages, choose **Show, All Pages**.

Error Type	Error (% of Span)	Significance (%)
Maximum Found	-0.008	1.6

Figure 78: Calibration Results window — first page

On the second page of the Calibration Results window, the user (Calibrated by) must be selected. If a calibration management software is used, the user list is transferred to the calibrator and the correct user can be selected. A new user can also be created by tapping the **Calibrated by** button and then pressing Create New button (.




Figure 79: Calibration Results window — second page






Figure 80: Calibration Results window - third page



The screenshot shows the 'RESISTANCE' window, page 4 of 5. It features a table with four columns: Input (Ω), Output (Ω), Error (% of Span), and Significance (%). The table contains five rows of data. On the right side, there are icons for a trash can (Delete), a floppy disk (Save), and a document with an arrow (Previous/Next), along with a page indicator '4 / 5'.

Input (Ω)	Output (Ω)	Error (% of Span)	Significance (%)
0.046	0.039	-0.007	1.4
25.048	25.040	-0.008	1.6
50.048	50.040	-0.008	1.6
75.048	75.041	-0.007	1.4
100.049	100.042	-0.007	1.4

Figure 81: Calibration Results window — fourth page



The screenshot shows the 'RESISTANCE' window, page 5 of 5. It displays environmental and temperature information. The 'Environment Information' section includes fields for kPa, °C, and % RH, all showing '---'. The 'Temperatures (°C)' section includes fields for Device (---), Input Calibrator (30.63), and Output Calibrator (30.63). The 'Time Spent' section shows '00:00:00'. On the right side, there are icons for a trash can (Delete), a floppy disk (Save), and a document with an arrow (Previous/Next), along with a page indicator '5 / 5'.

Figure 82: Calibration Results window — fifth page

You can save the results using the **Save** button () . Select whether the calibration is *As Found* or *As Left*. *As Left* result can be also combined with previous result by checking the **Combine with Previous Result** box. When enabled, the Calibration Management Software considers all combined results as a single calibration event with multiple repeats.

You can reject the result by pressing the **Delete** () button if you do not want to save it.

After saving or rejecting the results, the Calibration window opens (see [Figure 75: Calibration window](#)). You can either start another calibration repeat by tapping the **Start** button or finish calibration for this instrument by tapping the **Back** button.

Viewing Saved Calibration Results

After calibrating an instrument, you can view the saved calibration results, one instrument at a time. You can find the most recent result in the Instrument Overview window using the **View Results** button () . To browse all previously saved results, open the context-sensitive menu in the **Calibration Results** window and select **Results History**.




Figure 83: Calibration Results History window

Different shades of gray help distinguish separate calibration events. If the instrument's settings were changed, the background turns blue. Tap the entry to view the settings as they were at that date and time.



Note: Saved calibration results are read-only and cannot be edited.

Deleting Calibration Results

To delete calibration results, open the context-sensitive menu and choose **Manage**. Choose **Delete This Result** to remove the currently displayed result, or select **Delete All Results** to erase all results associated with the current instrument.

Alternatively, you can delete all results for the current instrument in the **Results History** window by choosing **Delete All Results** from the menu.

After the results have been successfully transferred to CMX or LOGiCAL, you can also delete them in the Calibration Management Software or Sync Client.



Note: To remove all calibration results for all instruments across all Plant Structure Levels, go to the Instrument List window, open the menu, and select **Manage > Delete All Results**.



Warning: Deleted results cannot be recovered.

Creating Instruments in MC6-WS

You can create a new instrument in Documenting Calibrator mode in one of two ways:

- Tap **Create New** instrument button (.
- Go to the Instrument List menu and select **Create New > Instrument**.

The MC6-WS calibrator includes these configuration pages:

- **Identification** – Defines the identification information of position and device.
- **Input, Output and Function** – Describe the instrument's measurement capability and define how input and output signals are captured.
- **Procedure** – Specifies calibration points and point acceptance method. Advanced settings allow for calibration notes and scheduling.
- **Error Limit** – Lets you select the error calculation method and define advanced error limits.

Table 4: Data location in Beamex Calibration Management Software

MC6-WS configuration pages	Corresponding entity in CMX	Corresponding tab in LOGICAL
Identification	Position, Device	Position tab, Device tab
Input	Function	Function tab, partly in Calibration Methods related to instrument type
Output		
Function		
Procedure	Calibration Procedure	Procedure tab
Error Limit		Error Limit tab



Note: Although several devices can be linked to one position in the Calibration Management Software, the calibrator only shows the data of the measurement device currently being calibrated.

By default, only the basic configuration pages are shown. To view all pages, select **Show > All Pages** from the context-sensitive menu when creating or editing an instrument. Note that page numbering will change accordingly.

Start creating an instrument and fill in the instrument data in all the fields.



Tip: You can automatically populate some of the smart instrument data when creating a new instrument in MC6-WS with the Get Mapped Values feature. For more information, see chapter [Get Mapped Values feature](#).



Note: MC6-WS allows instruments with identical identification, but this may cause issues when transferring the results to calibration management software, where instrument identifications must be unique (with exception of multi-function instruments).

Identification Related Data

The **Identification** configuration page allows you to define the Position ID, Position Name, Device ID, and Device Serial Number.



Note: The Device ID field is mandatory.

Figure 84: Identification configuration page

Instrument Function Related Data

The **Input** configuration page defines the input Quantity and related parameters.

Figure 85: Input configuration page

Port/Function (excluding Keyed) and **Unit** settings are available for all input quantities. Additional configuration fields may appear depending on the selected Quantity and Port/Function (see table below).


Table 5: Input parameters depending on the selected Quantity

Quantity	Additional settings available
RTD Temperature	Sensor Type
TC Temperature	Sensor Type, RJ Mode
Pressure	Pressure Type
Current	Loop Supply
Frequency	Amplitude, Waveform & Duty Cycle, Trigger Level
Pulse	Amplitude, Waveform & Duty Cycle, Frequency, Trigger Level, Trigger Edge
Keyed	Keyed Quantity, Resolution, Resolution from Entry



Note: When using MC6-WS calibrator with an external controller, select the controller on the Input page. For a pressure controller, select *Pressure* as the quantity and the controller in Port/Function.

By default, all generations begin when the calibration starts. If necessary, you can start the generation earlier by selecting **Initial Values** from the context-sensitive menu on any instrument configuration page.

**Figure 86: Initial Values functionality**


The image shows a software window titled "Initial Values" with a green header bar and a red close button in the top right corner. Inside the window, there are two input fields. The first field is labeled "Input: Current - OUT: Generation" with "mA" as the unit. The second field is labeled "Output: Keyed - Manual Entry" with "°C" as the unit. Both fields contain a dashed line "----" as a placeholder for text entry.

Figure 87: Initial Values window

The **Additional Supplies** (advanced configuration) page lets you choose an additional supply source (for Loop and/or Sensor).


The image shows a software window titled "Additional Supplies" with a green header bar. On the left of the header is a home icon and a menu icon, and on the right is the text "TT101" and a red close button. The main area of the window has two sections: "Loop Supply" and "Sensor Supply". Each section has a large button labeled "None". To the right of these buttons are three stacked buttons: an "Up" arrow button, a "3 / 11" button, and a "Down" arrow button. At the bottom right corner is a green button with a white checkmark.

Figure 88: Additional Supplies advanced configuration page

Use the **Output** configuration page to define the output signal Quantity and its parameters.




Figure 89: Output configuration page

For most Quantities, the same parameters as for Input are available, with a few additional settings (see table below).

Table 6: Additional Output parameters

Quantity	Additional available settings
Pulse	Zero
Switch	Switch Type, Switch Sound, Trigger Level
Keyed	Display Type

The **Function** configuration page allows you to configure the following:

- Input Range - lower and upper limits for the calibration reference signal.
- Transfer Function - defines the relationship between instrument's input and output (e.g. Linear, Square Root, etc.).
- Output Range - the lower and upper limits for the output signal.



Note: For measurement devices, the output range is the same as the input range.

- Function name.

Figure 90: Function configuration page

Calibration Procedure Related Data

Procedure configuration page allows you to define the following parameters:

- Calibration Points (Predefined) – specifies calibration points (number of steps, step size, and percentage) or select one of the predefined sets.
- Repeat Format – defines the way the calibration points are advanced.



Tip: The combination of Calibration Points and Repeat Format determines how many points are used and the order in which they are executed.

- Points are Input / Output – by default, calibration points are based on input. Tick this box to calculate them from output instead.
- Max Point Deviation (% of span) – allows deviation from the nominal calibration point value and works together with automatic point acceptance. If the input value stays within the defined tolerance, the point is accepted automatically and calibration continues. Otherwise, it requires manual acceptance.
- Stability Check – calibrator checks input signal stability before saving the reading. Tick this box to also check output stability.
- Point Delay (s) – sets the delay before a point is accepted, provided Automatic Acceptance is enabled.
- Automatic Acceptance – automatically accepts points after considering settings such as point delay, stability, etc.

The screenshot shows the 'Procedure' configuration window for device TT101. It features a title bar with a home icon, a menu icon, the title 'Procedure', the device ID 'TT101', and a red close button. The main area contains several configuration options: 'Calibration Points (Predefined)' with a value of '5: 25%'; 'Repeat Format' set to 'Up'; 'Points are Input / Output' with an unchecked checkbox and 'From Output' button; 'Max Point Deviation (%)' set to '4'; 'Stability Check' with a checked checkbox and 'Also for Output' button; 'Point Delay (s)' set to '5'; and 'Automatic Acceptance' with an unchecked checkbox and 'Use' button. On the right side, there are navigation buttons: an up arrow, a down arrow, and a green checkmark button. A status indicator '6 / 11' is visible between the up and down arrows.

Figure 91: Procedure configuration page

The **Notes** (advanced configuration) page can be used to enter calibration and adjustment notes.

The screenshot shows the 'Notes' configuration window for device TT101. It features a title bar with a home icon, a menu icon, the title 'Notes', the device ID 'TT101', and a red close button. The main area contains three text input fields labeled 'Before Calibration Note', 'Adjustment Note', and 'After Calibration Note'. On the right side, there are navigation buttons: an up arrow, a down arrow, and a green checkmark button. A status indicator '9 / 11' is visible between the up and down arrows.

Figure 92: Notes advanced configuration page

The **Scheduling** (advanced configuration) page includes options to set the calibration due date and configure the calibration interval. You can also define the interval unit and calibration repeat count.

Figure 93: Scheduling advanced configuration page

Error Limit Related Data

The **Error Limit** configuration page lets you choose the **Error Calculation Method** (unit and reference), and set measurement error limits. It also provides a place to set up multiple error limits for the instrument (the instrument range can be divided up to 10 subranges, each having their own constant and relative error values).

Figure 94: Error Limit configuration page

The **Other Error Limits** (advanced configuration) page helps you define additional error limits and possible instrument adjustment settings.

Other Error Limits TT101

Adjust if Error > (% of 'Reject if Error >')

0

Don't Adjust if < (% of 'Reject if Error >')

0

Adjust to < (% of 'Reject if Error >')

0

8 / 11

Figure 95: Other Error Limits advanced configuration page

Device Related Data

The **Device** configuration page lets you specify the Location, Sensor Serial Number, Manufacturer, and Model.

Device TT101

Location

Sensor Serial Number

Manufacturer

Model

11 / 11

Figure 96: Device advanced configuration page

Group Calibration

The **Group Calibration** feature in the Documenting Calibrator lets you calibrate several instruments or functions individually, in sequence. This is especially useful when calibrating instruments or functions that are part of a loop or when input generation takes time (e.g., with temperature), and several devices need to be calibrated in one session.



Note: Grouped instruments may be created directly in MC6-WS or received from CMX or LOGiCAL. However, groups can only be created in the calibrator itself, not in the calibration management software.



Tip: Examples of instruments and functions that are suitable for Group Calibration include:

- A measurement loop consisting of a temperature transmitter, a local temperature indicator, and a temperature indicator in the control room.
- A set of temperature sensors calibrated simultaneously using, for example, a dry block.



Note: The Group Calibration feature does not support switches.

Creating and Editing a Group

Collecting Instruments or Functions for Group Calibration

You can create a group in the Instrument List window. Open the Instrument List menu and select **Create New > Group**.




Figure 97: Creating a group

To add an instrument or function to the group, select it in the Instrument List view to open the Instrument Overview window and then press the **Add to Group** button ().




Figure 98: Instrument Overview window – Add to Group button

Instruments included in the group will have a blue background in the Instrument List.



Figure 99: Grouped instruments

Once an instrument is added to the group, MC6-WS goes back to the Instrument List to allow selection of additional instruments. By default, calibration proceeds in the order the instruments or functions were added to the group.

Tap the **Group Info** button (☰) to view all grouped instruments in the Group Overview window.




Figure 100: Group Overview window

Editing a Group

You can rearrange the order using the context-sensitive menu in the Group Overview window.




Figure 101: Group calibration – calibration order for the grouped instruments



Note: Selecting **Instrument Order** > **Optimize** will automatically sort the group so calibration starts with the instrument having the lowest calibration point.

To modify instrument configuration data for individual instruments, open the context-sensitive menu in the Group Overview window and select **Instrument** > **Settings**. The same menu also allows you to **Cancel Group** or remove the selected instrument or function from the group using the **Instrument** > **Remove from Group** option.



Note: When Group Calibration is active, the **Configure** (⚙️) and **View Results** (📄) buttons become options in the Group Overview window's context-sensitive menu.

Calibrating a Group

After you define a group, start the calibration process by tapping the **Accept** button (✅) in the Group Overview window. The **Calibration** window opens and displays the first instrument or function in the group.

Tap the **Start** button to begin the calibration.



Note: The **Info** button in the Calibration window now indicates which instrument or function is currently shown (see [Figure 103: Calibration window – Settings and Group Settings](#)). Press the button to view the instrument configuration data and connection diagrams.



Figure 102: Group calibration – instrument selection button



Note: To change the calibration order, tap the **Info** button and select a different instrument or function in the Group Overview window.




Figure 103: Calibration window – Settings and Group Settings

Before starting the group calibration, make sure to review the settings. Select **Functions** > **Settings** to access advanced options, such as such as displaying the **Function Name** in the Title bar. Descriptive function names can help identify instruments and functions more easily when calibrating items in a loop.

More details about group settings are available in section [Group Settings](#).



Note: Remember to change the connections if needed when the instrument or function changes during the group calibration.

After all instruments or functions have been calibrated, the Calibration Results window opens and indicates whether the calibration **Passed** or **Failed** for each instrument or function individually. The results are shown on multiple

pages, offering different views of the calibration data, such as numerical values, graphical representation, and general information.

You can save the results using the **Save** button () . Select whether the calibration is *As Found* or *As Left*. *As Left* result can be also combined with previous result by checking the **Combine with Previous Result** box. When enabled, the Calibration Management Software considers all combined results as a single calibration event with multiple repeats.

You can reject the result by pressing the **Delete** () button if you do not want to save it.

After saving or rejecting the results, the Group Overview window opens (see [Figure 100: Group Overview window](#)). You can either start another calibration repeat by tapping the **Accept** button or return to the Instrument List to, for example, add or remove instruments or functions from the group.

Group Settings

To open the **Group Settings** window, select **Functions > Group Settings** from the context-sensitive menu in the Calibration window (see [Figure 103: Calibration window – Settings and Group Settings](#)).




Figure 104: Group Settings window

Group Settings allow you to define the **Calibration Point Sequence**, which defines how calibration points are progressed through. Two options are available:

- By Group: Suitable when all instruments in the group have the same input range. The number of calibration points can vary, as long as the range is the same.
- By Value: Suitable for instruments with different spans. **The first instrument must have the lowest calibration point in the group.** If needed, use the sorting tool described in section [Editing a Group](#).

The **Show Instrument Info Dialog** setting determines when the Instrument Overview window is displayed during Group Calibration.

Special Use Cases

The Documenting Calibrator offers versatile functionality and supports a wide range of use cases.

In some situations, the calibration range exceeds the measurement range of a pressure module or the control range of an external controller. In these cases, the pressure module or controller must be changed during the calibration process.

If instruments have been sent from CMX Calibration Management Software, you can use the Work Order View as an alternative way to access the instrument list. These special scenarios are described in the following subchapters.

Changing a Pressure Module During Calibration

If a calibration involves using multiple pressure modules, you will need to change them "on the fly".

To change a pressure module during calibration:

1. Open the context-sensitive menu and choose either Instrument Input or Instrument Output, depending on where the module is connected.
2. Tap the **Port/Function** button and select the new pressure module from the list. If switching from one external pressure module to another, tap the **Change external pressure module** button () and follow the instructions shown on the display.

Using External Controllers in Calibration

Using an MC6-WS together with a pressure controller or a temperature dry block enables fully automated calibration of various pressure and temperature instruments. To use the external controller in Documenting Calibrator, first pair it with the calibrator and define the required presets. For instructions, see chapter [Enabling Communication with the Controller](#).

Pressure Controller

When using a pressure controller, select Pressure as the Input Quantity. To run the controller in full Controller mode, select it in Port/Function. In this mode, the controller sets the pressure setpoints and measures the reference pressure.

To use MC6-WS internal pressure modules as the reference, choose the appropriate internal or external module in Port/Function. The Input page will display a prompt asking whether the controller should set the calibration points – activate the tickbox to confirm.

Temperature Dry Block

When working with a temperature dry block, the quantity selection depends on how the reference temperature is measured:

- Full Controller mode – the dry block controls setpoints and measures reference temperature. Select Temperature as Input Quantity and the dry block in Port/Function.
- MC6-WS as a reference – MC6-WS measures the reference temperature. Select RTD Temperature or TC Temperature as Input Quantity.

The Input page will display a prompt asking whether the controller should set the calibration points – activate the tickbox to confirm.

Details on the methods can be found in chapter [Calibration Methods with External Controllers](#).

Changing a Controller During Calibration

Sometimes, calibration requires changing a controller during the process (for example, when the dry block's temperature range doesn't cover the instrument's full measurement range).

To change the controller during calibration:

1. Open the context-sensitive menu and choose **Instrument Input**.
2. Then tap the **Change Controller** button () in the Instrument Input window and follow the instructions shown on the display.

Work Order View Mode

Work Order View Mode offers an alternative way to view the instrument list when instruments are sent from CMX Calibration Management Software along with Work Orders in their Calibration Procedure. To activate Work Order View Mode, open the context-sensitive menu in the Documenting Calibrator Home view and select **Work Order** from the View Mode options.




Figure 105: Activating Work Order View Mode

When Work Order View Mode is enabled, a list of Work Orders is shown.




Figure 106: List of Work Orders

Legend:

1. Work Orders list (green background with light blue stripes indicating Work Order View Mode).
2. Start and End Dates.
3. Work Order Number.
4. Number of Instruments included in each Work Order.
5. **Create New** instrument button (📄).
6. Instrument without a Work order number.



Tip: Instruments without a Work Order number are displayed below the list of Work Orders.

Tapping a Work Order opens its list of instruments.




Figure 107: Instrument belonging to Work Order

Legend:

1. Instruments in a Work Order (highlighted with light blue stripes for Work Order View Mode).
2. Function Name.
3. Position ID.
4. Work Order Start and End Dates.
5. Work Order number.

Selecting a Work Order gives options in the context-sensitive menu to delete results of the current Work Order or remove the entire Work Order.

Calibrating an instrument within a Work Order follows the same procedure as with any other instrument.



Note: The Instrument Overview window displays the associated Work Order details within the instrument's general information and on a dedicated page. Work Order data such as number and dates are read-only in MC6-WS.



Note: When Work Order View Mode is active, the Plant Structure is hidden, and you cannot move or copy instruments in the structure.

Mobile Security Plus Option

Beamex Mobile Security Plus technology helps maintain the integrity of calibration data even when calibrations are performed offline. Authentication is done with the CMX user ID and the mobile device password set by the user in CMX, ensuring protection against unauthorized data changes.

The Mobile Security Plus feature requires CMX Calibration Management Software version 2.11 or later, with Mobile Security Plus option installed in both CMX and the calibrator. For more information about Mobile Security Plus functionality, please refer to the *CMX User Manual*.

Applied Restrictions

Depending on the CMX configuration, the following Documenting Calibrator functions are either restricted by admin credentials or completely disabled:

- **Skipping** or **undoing** calibration points.
- **Rejecting** (exiting) incomplete calibrations without saving the results.
- **Changing** the date and time on the calibrator
- **Modifying** the calibration date and time of a keyed calibration.
- **Deleting** calibration results.
- **Deleting** an instrument that has saved calibration results.




Figure 108: Message shown by the calibrator when functionality is blocked



Note: Changing Regional Settings and Date & Time also requires admin credentials.

Data Logger

The **Data Logger** is an optional user interface mode that allows you to collect data with MC6-WS. The **Data Logger** supports logging up to nine channels simultaneously, including measurements, generations, or simulations.

You can view the data log results in numerical or graphical format and transfer them to a PC for further analysis using the **Beamex MC6 Data Log Viewer** (for details, see subchapter [Data Log Viewer](#)).



Note: In many industrial settings, signals need to be measured over a period of time and the results stored for later analysis, such as for troubleshooting, monitoring, or calibration.

If the Data Logger option is not installed on your MC6-WS, the icon in the Home View will appear disabled. To upgrade your calibrator, please contact Beamex.

To start the Data Logger mode, tap the **Data Logger** button in the Home view.




Figure 109: Home view, Data Logger user interface mode

Configuring a Data Log

Make sure to define the general settings before starting your data log. Tap the grey area in the bottom-left corner of the main configuration window to open the **General Configuration** window. There, you can set how data is logged, what

values are saved, and how long the logging will run, among other configurable parameters.

Instant	1 s
Periodic	301 Pcs
⌚ 0:00:10	0:05:00

Figure 110: Data Logger – General Configuration window button

The start of data logging depends on the general settings:

- **Delayed Start** – You may configure a delay before logging begins, either as a countdown (e.g., 5 minutes) or a scheduled start time (e.g., 5:15 PM). During the delay, an hourglass icon with a countdown will be shown.



Note: After the delay, any channel-specific triggers may further delay the start. Logging begins as soon as one of the triggers is activated.

- **Logging Method** – Choose how data is logged. The **Periodic** method allows automatic logging based on additional settings. The **Key Press** method enables manual logging.



Note: If **Key Press** is selected, data is logged each time you tap the **Manual Trigger** button (). In this case, any channel-specific triggers will be ignored.

To configure a channel, tap one of the numbered areas in the **Data Logger's** main configuration window.




Figure 111: Three configured channels in the main configuration window

Each channel can be set up independently. Measurement channels include three configuration pages, while generation and simulation channels have two:

- Measurements/generations/simulations: A page used to define the quantity being measured, generated, or simulated, along with its additional settings.




Figure 112: Data log Channel Setup window – 1st page

- Measurements/generations/simulations: A page that lets you configure the graph range, enter an optional function name, and select the color of the plot.

- **Measurements:** A page for defining a trigger that starts data logging. When a trigger is configured, a trigger symbol () appears in the channel area.




Figure 113: Data log Channel Setup window – 3rd page

In this example, all four trigger methods are active. You can use just one or combine several. If multiple methods are enabled, they are combined using a **logical OR**, and data logging begins as soon as one of the following is TRUE:

- The measured value is larger than 4.0
- The measured value is smaller than 20.0
- The rate of change exceeds 5
- The rate of change drops below -5



Note: When using pressure modules, you can zero the gauge module either through the context-sensitive menu in the main configuration window or directly in the Channel Setup window, if available.

Saving and Opening Configurations

MC6-WS remembers your latest data log settings, and you can also save custom configurations. To save or open a previously saved configuration, open the context-sensitive menu in the main configuration window and select **Configuration > Open Configuration/Save as**.

Logging Data

To start the data log, tap the **Record** button () in the main configuration window. The button will change to a **Stop** button (), allowing you to stop the log at any time.



Note: The actual start of data logging depends on the general settings. See [Configuring a Data Log](#).




Figure 114: Counting down the delay

To change a generation or simulation value during data logging, tap the channel and enter a new **Set Value**.



Tip: You can switch between the main configuration window and the graph view by tapping the toggle area in the title bar.



Figure 115: Toggle area in the title bar (highlighted in yellow)




Figure 116: Graph view during a data log

Data Log Results

After data logging has been finished or stopped, the Result Preview window shows the data log results across three pages: general information, a graph, and a numeric table.



Tip: For large numeric tables, use scroll buttons or the scroll bar to access any hidden rows and columns.

Results Preview				
Time	OUT		P1	TC1
30-12-2024	(mV)		(mmH ₂ O)	(°C)
09:30:09	Instant		Instant	Instant
09:30:09	3.20		12	96.89
09:30:10	3.20		13	96.71
09:30:11	3.20		13	96.59
09:30:12	3.20		13	96.45
09:30:13	3.20		13	96.32
09:30:14	3.20		12	96.19
09:30:15	3.21		13	96.05
09:30:16	3.21		13	95.95
09:30:17	3.20		13	95.77

Figure 117: Data log Results Preview window



Note: MC6-WS automatically adds a timestamp (date and time) to each data log result.

On each page, you can either **Save**  or **Delete**  the data log results.



Tip: When saving, you can give the data log results a descriptive name.

Viewing Saved Data Log Results

To view previously saved data logs, go to the main configuration window in the Data Logger and select **View Data Log Results** from the context-sensitive menu.




Figure 118: Data log Results list

Each saved log displays its time, date, and result name in the top row. The bottom row shows the file size and, if available, the name of the configuration used.



Tip: You can use the context-sensitive menu in the Data Log Results window to **Delete All** saved data log results.

When viewing a specific result, the menu also offers options to **rename** or **delete** the selected log.

Data Log Viewer

Beamex MC6 Data Log Viewer is a free PC tool used to transfer data log results from MC6-WS to a PC. You can download the MC6 Data Log Viewer under the Resources tab on the [MC6-WS product page](#) on the Beamex website.

After installing the MC6 Data Log Viewer on your PC, open the program and connect the calibrator using a USB cable. The tool will automatically detect the calibrator, provided it is powered on. You can then download and view the results from the MC6-WS calibrator. Data can be saved in the tool's native format (.LG6) or exported as .CSV files, which can be easily imported into spreadsheet programs.




Figure 119: Beamex MC6 Data Log Viewer

Communicator

The MC6-WS calibrator can be used as a fieldbus communicator to calibrate, configure, and trim your smart instruments. The **Communicator** is an optional user interface mode that allows you to connect with smart instruments, using one of the following communication protocols:

- **HART** (MC6-WS supports HART instruments using HART Protocols 5 and 7);

(<https://www.fieldcommgroup.org/>)

MC6-WS can be used as a primary or secondary master of a segment.

- **FOUNDATION Fieldbus H1**;

(<https://www.fieldcommgroup.org/technologies/foundation-fieldbus/>)

MC6-WS is seen as a guest device (visitor) and, when necessary, as a secondary master of a segment using Link Active Scheduler (LAS).

- **PROFIBUS PA**;

(<https://www.profibus.com/>)

MC6-WS takes the role of PROFIBUS master when connected to a PROFIBUS segment.

To start the Communicator mode and see the communication protocols installed in your calibrator, tap the **Communicator** button in the Home view. If your MC6-WS does not have communicator options installed, the Communicator icon in the Home View will be disabled. Contact Beamex for an upgrade.




Figure 120: Home view, Communicator user interface mode

All three communication protocols can be installed simultaneously, and the Communicator user interface mode is activated if any of the three protocols is installed. The Communicator mode is primarily meant for viewing and editing the configuration of smart instruments. The three supported communication protocols are available as a quantity in Calibrator, Documenting Calibrator and Data Logger user interface modes. For more information on smart instruments see chapter [Working With Smart Instruments](#).




Figure 121: Communication protocols



Note: Each fieldbus communication protocol is a separate option, therefore not all protocols are necessarily enabled in your MC6-WS calibrator.

This manual is not intended as an introduction to HART and fieldbus instruments. For basic knowledge and terminology, refer to books specifically dedicated to HART and fieldbus technology.

The Communicator user interface may display text in a language different from the language set up in the MC6-WS settings. The language of the instrument's fields etc. may differ from MC6-WS calibrator's language.

Device Description Files

Device Description (DD) files describe the smart instrument functionality and are required for communication. The MC6-WS calibrator supports hundreds of HART and fieldbus devices from dozens of manufacturers, depending on the Communicator options installed. If a specific device is not supported, MC6-WS uses the generic DD file that only supports basic functionalities.

To view DD files currently installed in the calibrator:

1. Open **Settings** and select the protocol (HART / FOUNDATION Fieldbus H1 / Profibus PA).
2. In the context-sensitive menu, choose **Available Device Descriptions**. The calibrator will show a list of DDs by manufacturer, with the option to view each file individually.




Figure 122: Context-sensitive menu – Available Device Descriptions

New DD files for the MC6-WS are released regularly. When available, they can be downloaded from the Beamex website and installed in your calibrator using the **MC6 Device Description Installer** tool. Each DD package includes a release note listing all supported devices and the DDs added in the latest package. Downloads are available under the Resources tab on the [MC6-WS page](#) on the Beamex website.



Note: It is not possible to download DD files from the smart instrument manufacturer's website and install them directly onto the calibrator. The DD files must be downloaded from the Beamex website.

Device Descriptions settings

Using device-specific DD files is the recommended method. However, for HART or Profibus PA it is also possible to define that a Generic or Standard Profile DD file should be used, even though a device-specific DD file would be available. For FOUNDATION Fieldbus H1, only the Device Specific DD files can be used. A simplified method for using HART instruments, called Basic View, is also available. The default setting of Active Device Descriptions can be defined in MC6-WS Settings.




Figure 123: Communication protocol settings in MC6-WS Settings mode

MC6-WS supports three kinds of Active Device Descriptions for smart instruments:

- **Device Specific**, i.e. custom DD file for smart instrument, stored in MC6-WS memory. Full instrument data is available.
- **Generic**, i.e. a library of Common DD files applying to most HART instruments. Only a standard set of instrument data is available.



Note: Profibus PA: this option is called Standard Profile.

- **Basic View**, a simplified HART DD file available in MC6-WS.




Figure 124: Active Device Descriptions window

 **Note:** You can also define the Active Device Descriptions method in other user interface modes by pressing **Tools** button () in the Supply view for selecting output Quantity. This option is available in **Calibrator**, **Documenting Calibrator**, **Data Logger** and **Communicator** user interface modes.




Figure 125: Tools button in Supply view for selecting output quantity

Basic View

The Basic View window presents the instrument's Value Parameters, basic Device Setup settings, and Process Variable settings. You can select any available value parameter for calibration, data logging etc.




Figure 126: HART Basic View window example

Editable fields are presented in the following examples of Device Setup window and Process Variable Settings window.





Figure 127: HART Device Setup window example



Process Variable Settings

Transfer Function

Linear

Unit

°C

Damping (s)

0.4

Sensor Serial Number

823097

Range

0 0% 150 100% kPa

Range Limits

-200 ... 850 / 10

Figure 128: HART Process Variable Settings window example



Note: HART trimming is not supported using Basic View DD file. Use another Device Description method when trimming a HART instrument.

Managing Smart Instrument Configurations in MC6-WS

You can manage smart instrument configuration data using MC6-WS and a free PC tool - **Beamex MC6 Fieldbus Configuration Viewer**. You can download the MC6 Fieldbus Configuration Viewer under the Resources tab on the [MC6-WS page](#) on the Beamex website.




Figure 129: Beamex MC6 Fieldbus Configuration Viewer



Note: With **Fieldbus Configuration Viewer**, you can:

- Load the configuration files from MC6-WS calibrator
- View the configuration files
- Save the configuration files in PC (e.g. proprietary *.fc file).
- Print the configuration files

Saving Configurations

You can save the instrument's configuration data when connected to a smart instrument. Open the context-sensitive menu and select **Configuration > Save As** to download all configuration data. After configuration download is completed, MC6-WS will prompt you to give the configuration file a name. The default file name is the smart instrument's Tag name.




Figure 130: Smart instruments – saving the configuration

This feature is handy especially when you have an analog DCS (Distributed Control System) and HART smart instruments in the field. You can use this functionality to create a database of all the configuration files of your smart instruments. If a transmitter breaks, all settings are stored in MC6-WS (alternatively on a PC), for an easy configuration of the new transmitter replacing the broken one.



Note: It is not possible to upload the saved configuration file from MC6-WS back to the transmitter.

Viewing or Opening Configurations

You can open the list of saved configurations anywhere in **Communicator** mode. Open the context-sensitive menu and select **Configuration > Open Configuration** to display the list of saved configurations.



Note: Saved configurations can also be opened in the communication protocol selection window, where no protocol has been selected yet.




Figure 131: Open Configuration option in protocol selection window

The list shows the following information about each saved configuration file:

- Name of the file
- Manufacturer/Model
- Date/Time when saved
- Protocol name

You can sort the list of configurations with the help of the sorting tools available in the context-sensitive menu. Tap on a configuration to view the saved configuration data.



Note: The configuration file data cannot be edited.

Linking Configurations to CMX

If applicable, the configurations can also be sent to **CMX Calibration Management Software**, as linked documents in a Position/Device field. Use this feature to link the *.fc files to CMX. Double click the link to open the configuration file in the Fieldbus Configuration Viewer.

Working With Smart Instruments

Smart instruments are advanced devices equipped with digital communication capabilities and microprocessors. To work with smart instruments, you need to establish a connection. This enables communication, access to data, and the ability to perform tasks such as configuration, calibration, and diagnostics.

In MC6-WS you can start communication with a smart instrument from the following user interface modes:

- **Communicator,**
- **Calibrator,**
- **Documenting Calibrator,**
- **Data Logger.**

When creating a new instrument in Documenting Calibrator using fieldbus or HART instruments' digital output, select HART, FOUNDATION Fieldbus H1, or Profibus PA as the Output quantity. In other user interface modes where communication may be started, the communication protocols are available in the Quantity selection window. See the picture below.




Figure 132: Quantity selection window in Documenting Calibrator mode



Note: For the analog output of a HART instrument, select **Current** as the Output quantity.

See also chapter [Get Mapped Values feature](#).

Additional Options During Calibration

The context-sensitive menu in the Calibration window offers additional options available. For both HART and fieldbus instruments, you can start the Communicator mode to edit instrument data and, if needed, start a HART trim method. Additionally, for fieldbus instruments, there is a specific option for trimming the instrument.




Figure 133: Context-sensitive menu options in HART instrument Calibration window

About Smart Instrument Parameters

This chapter briefly describes how to view, configure and access the smart instrument data in MC6-WS.




Figure 134: Blocks and Parameters view example in MC6-WS

Legend:

1. **Blocks and Records**- may contain sub-blocks, sub-records, editable parameters and read-only parameters. Tap on the Block/Record to see its contents.
2. **Editable parameters** - fields that can be numeric, text, single select, multi select or date type. Tap to edit the field data.
3. **Read-only parameters** - data that you may view/read but cannot edit. The "lock" icon indicates that the parameter cannot be edited.
4. **Value parameter** - a special case of the read-only parameter. The Value parameter is a live measurement and cannot be edited, but it can be opened for viewing and selected for use in **Calibrator**, **Documenting Calibrator** or **Data Logger** modes.
5. **Methods** - automated procedures for e.g. calibration of HART instruments. Note that the word "Method" helps to distinguish a method from a parameter.



Note: Select **Show > Measurable Variables** from the context-sensitive menu to display only the Value parameters.



Note: If you select a Value parameter and you started the communication from **Communicator** mode, the value is taken into use in **Calibrator**. If you started the communication from any other supported user interface mode, e.g. **Data Logger**, the selected Value parameter is taken into use only in that particular user interface mode.

Editing Parameters

Editing parameters means changing any editable parameter in the instrument's memory, such as selecting the type of process connection fitted to the instrument.

Tap on a parameter to start editing it in a new window. The type of window depends on the type of parameter selected for editing, e.g. a selection list, a text or a numeric field.

When you edit a parameter that is not a part of a record containing several parameters, the edited value is sent to the instrument as soon as you press the

Accept button (✓).

HART instruments: If a parameter is part of a record (i.e. several parameters together), each parameter can be edited separately. However, the edited values are not sent to the instrument until the **Accept** button (✓) of the record window is pressed. Prior to sending, edited parameters have a blue background.

Sensor Information	
Isolator Material	316L
Fill Fluid	Silicone Oil
Gasket Material	316L
Process Connection Size	1/2NPT Male
Process Connection Material	316 SST
Process Connection Type	Conventional

Figure 135: Sensor Information record example



Note: This manual explains how the parameters can be accessed and viewed using MC6-WS calibrator. For detailed information on smart instrument data, refer to the manual of the instrument itself.

Beamex cannot be held responsible for any damages caused by changing parameters of smart instruments.

Selecting Instruments

When a communication protocol is selected, a window opens to choose whether to use the MC6-WS internal 24 V supply or an external supply. Additionally, with the FOUNDATION Fieldbus H1 protocol, you need to specify whether you are connecting to an offline device or a device that is part of a live segment.




Figure 136: External supply voltage for FOUNDATION Fieldbus H1 for LIVE segment use

When using an external supply, ensure communication by using either a HART or fieldbus compliant power supply or by adding a suitable resistor between the power supply and the bus. Check the chapter [Smart Instrument Connections](#) and consult your power supply's manual for detailed instructions.

Additionally, there is a **Tools** button (🔧) for editing or checking the **Protocol Settings**. You can also access the protocol settings through the Settings user interface mode.



Note: If HART instrument is not found, it might be because of low loop impedance. Increasing the signal sensitivity might help improve communication.

Normal Sensitivity setting follows HART specifications, while High Sensitivity option allows the calibrator to send stronger signals and detect weaker ones. To change the Sensitivity, go to **Settings > HART** and set it to **High**.




Figure 137: HART Sensitivity settings

The default settings should apply, so avoid making changes unless you are certain. In case of communication issues, refer to the HART or fieldbus instrument's manual.

See also chapter [Device Description Files](#).

List of Found Devices

After selecting the supply voltage, MC6-WS searches (monitors) for connected instruments and opens a window displaying a list of found devices. The window includes a **Refresh** button (🔄) to restart the search for connected instruments.

The **Configure** button (⚙️) allows you to quickly edit the tag and address for the listed instruments. When edit mode is activated, the instrument's background changes to blue.




Figure 138: List of found devices

To connect to the instrument, simply tap on its name in the displayed list. The MC6-WS calibrator will then retrieve the instrument's data, save it in its memory, and display the information when it is ready.



Note: If the MC6-WS calibrator does not have the Device Description file for the selected instrument, a **Device Description Missing** window will appear to notify you of the situation. Further information on downloading new DD files is available in chapter [Device Description Files](#).



Warning: When the calibrator is searching for connected fieldbus or HART instruments in the segment, DO NOT disconnect or reconnect the calibrator to or from the segment. Doing so may cause the segment to become unstable.

Get Mapped Values feature

The Get Mapped Values feature allows you to automatically populate some of the instrument data when creating a new instrument in MC6-WS. This is particularly useful for long data fields, as they don't need to be manually entered into the MC6-WS.

The MC6-WS includes default mappings for smart instrument fields, but you can customize the mapping configuration for each instrument model you use.



Note: To use this feature, make sure that your MC6-WS has the necessary communication protocol installed. It should correspond to the type of the connected smart instrument.

To populate the CMX or LOGiCAL Instrument database, simply map the instrument data to MC6-WS first, and then transfer the instruments to CMX or LOGiCAL.



Note: To transfer instruments, the user must have the permission to create instruments in CMX or LOGiCAL.

Preparations

You can map data to either a new instrument or an existing instrument in MC6-WS. The instrument's Output should be one of the following:

- Current (measurement),
- HART,
- FOUNDATION Fieldbus H1,
- Profibus PA.



Note: When the instrument's Output is set to Current Measurement, communication is possible only with the HART instrument at poll address 0.

Mapping the Instrument Data

To map the instrument's data when creating a **new instrument**, follow these steps:

1. Open the Documenting Calibrator mode and connect the smart instrument leads.
2. Select a communication protocol as the Output.
3. Specify the supply voltage.
4. Choose the instrument from the list of found devices.
5. Select the correct Value Parameter for calibration. The MC6-WS will automatically return to the Output configuration page for creating instrument.
6. Open the context-sensitive menu and tap **Get Mapped Values**.

To map the instrument's data for an **existing instrument**, follow these steps:

1. Open the Documenting Calibrator mode and connect the smart instrument leads.
2. Select the instrument from the Instrument List.
3. Select supply voltage and wait for the instrument to connect.
4. Tap **Configure** button ()
5. Open the context-sensitive menu and select **Get Mapped Values**.



Note: Always review the mapped instrument data.

The default mapping settings can be customized. For more information check chapter [Customizing the Mappings](#).



Note: For HART instruments, the input setting is automatically read from the transmitter. For other instruments, you need to manually add the instrument's input data.

Customizing the Mappings

You can customize the mappings on two different levels: protocol level (Protocol Defaults) for **HART**, **FOUNDATION Fieldbus H1** or **Profibus PA**, and device model level (Device Model Defaults). Customizable settings for both levels can be found under context-sensitive menu option **Mapping**.




Figure 139: Customizing mappings

MC6-WS uses the **Protocol Defaults** if no device model mappings are defined for the connected device model. However, if **Device Model Defaults** are defined for the connected device model, they are used instead of the **Protocol Defaults**. For both levels, you can either edit an existing mapping or add a new one.




Figure 140: Protocol Default mappings example for HART instrument

Legend:

1. Protocol Defaults mappings.
2. Target field in MC6-WS.
3. Mapping mode.
4. **Create new** button (📄★).
5. Value of the connected instrument's field.
6. Name of the connected instrument's field.

To edit a mapping, simply tap on it. To create a new mapping, tap the **Create New** button (📄★). Both actions will open the Field Mapping window, where you can either edit the existing mapping or create a new one.

Figure 141: Field Mapping window

In the Field Mapping window, you can configure the following settings:

- **Target Field** is the field in MC6-WS to which data will be mapped.
- **Value** is the field and its value in the connected device that will be mapped.
- **Mapping Mode** is the method used for mapping.

There are three available Mapping Modes:

- **Generic:** Displays a list of common fields from the protocol.




Figure 142: Available Value list in Mapping mode Generic

- **Text:** Assigns a fixed text value to the selected MC6-WS field.




Figure 143: Text editing in Mapping Mode Text

- **DD Field:** Provides a list of all fields available in the device model's Device Description file.



Note: This mapping mode can be used only with Device Model Defaults and is not supported for Protocol Defaults.



Tip: You can map the same transmitter field into several MC6-WS fields. For example, a device's Tag can be mapped both to Position ID and Device ID in the MC6-WS instrument data.

When adding or editing a mapping, target fields that are already in use are disabled (grayed out). Once you change the mapping, it will be saved as the default for future use. After modifying the mapping, you need to read the data again using the **Get Mapped Values** menu command.



Note: To delete a single mapping line, open it and press the **Delete** button (.

Calibrating Smart Instruments

Calibrating or Data Logging HART Instruments

Calibrating HART Instruments

To create a **new HART instrument** for calibration, follow these steps:

1. Select the **HART** communication protocol as the Output.
2. Browse the list of blocks, records, and parameters to locate the Value Parameter you want to select.



Note: Use the context-sensitive menu to select **Show > Measurable Variables**, which will display only the Value Parameters. Remember that Value Parameters have a green background.

3. Tap the **Accept** button () to confirm your selection.
4. The MC6-WS will return to the instrument configuration pages. Continue to configure the instrument data.
5. Follow the calibration process described in chapter [Calibrating an Instrument](#).




Figure 144: Variable list example in HART transmitter

For the **existing instruments**, select the instrument from the Instrument List.

Data Logging for HART Instruments

To configure a channel for HART instrument data logging, follow these steps:

1. Tap the channel you want to configure.
2. Set **HART** communication protocol as the Quantity.
3. Select the supply voltage.
4. Choose the instrument from the Instrument list.
5. Browse the list of blocks, records, and parameters to locate the Value Parameter you want to select.



Note: Use the context-sensitive menu to select **Show > Measurable Variables**, which will display only the Value Parameters. Remember that Value Parameters have a green background.

6. Tap the **Accept** button (✅) to confirm your selection.
7. Start logging the data.



Note: Unfortunately, the structure of data and naming conventions in HART instruments vary between different makes and models.



Tip: Refer to your instrument's manual to find the blocks where the parameters are located.

Calibrating or Data Logging Fieldbus Instruments

This is a quick guide for selecting a **FOUNDATION Fieldbus H1** or **Profibus PA** instrument's Value Parameter for calibration or data logging. If you want to make more extensive configurations, refer to the chapter [About Smart Instrument Parameters](#) and the manual of your instrument at hand.

Calibrating Fieldbus Instruments

To create a **new fieldbus instrument** for calibration, follow these steps:

1. Select either **FOUNDATION Fieldbus H1** or **Profibus PA** communication protocol as the Output.
2. Browse the list of blocks, records, and parameters to locate the Value Parameter you want to select.



Tip: The typical name of the Block (folder) where measurement parameters are located is **Transducer**. However, the Block name can vary depending on the instrument. If you are uncertain, refer to your instrument's user manual for guidance.



Note: Use the context-sensitive menu to select **Show > Measurable Variables**, which will display only the Value Parameters. Remember that Value Parameters have a green background.

3. Tap the **Accept** button () to confirm your selection.
4. The MC6-WS will return to the instrument configuration pages. Continue to configure the instrument data.
5. Follow the calibration process described in chapter [Calibrating an Instrument](#).




Figure 145: Accepting a parameter

For the **existing instruments**, select the instrument from the Instrument list.

Data Logging for Fieldbus Instruments

To configure a channel for fieldbus instrument data logging, follow these steps:

1. Tap the channel you want to configure.
2. Set **FOUNDATION Fieldbus H1** or **Profibus PA** communication protocol as the Quantity.
3. Select the supply voltage.
4. Choose the instrument from the Instrument list.
5. Browse the list of blocks, records, and parameters to locate the Value Parameter you want to select.



Note: Use the context-sensitive menu to select **Show > Measurable Variables**, which will display only the Value Parameters. Remember that Value Parameters have a green background.

6. Tap the **Accept** button (✓) to confirm your selection.
7. Start logging the data.



Tip: Refer to your instrument's manual to find the blocks where the parameters are located.

Trimming Smart Instruments

One of the most valuable benefits of calibrating smart instruments with MC6-WS is that it can also be used for trimming the instrument.



Tip: Remember to perform As Left calibration after trimming.

Trimming a HART Instrument

Trimming a HART instrument can only be started from the Communicator user interface mode. However, you can access the Communicator mode from other user interface modes by selecting **Start Communicator** in the context-sensitive menu (see [Figure 133: Context-sensitive menu options in HART instrument Calibration window](#)).

To locate and start a trimming method for both analog and digital signals or sensors, refer to the instrument's user manual. Once you have found the method, follow the provided instructions.



Note: Typically, the correct order for trimming is to start with the digital output first, followed by the analog output.




Figure 146: Sensor trim method

At some point during the trimming process, you will need to apply an applicable input signal.




Figure 147: Trim method in progress – channels (1) and (2)

Trimming procedure started in the Documenting Calibrator mode:

- The lower part of the window will display channels showing the instrument's input (1) and possibly also the output (2) readings. Use the input signal channel to verify the correct reading.

Trimming procedure started in another MC6-WS user interface mode, such as Communicator:

- Tap on one of the channels reserved for the calibrator readings and select a suitable Quantity for measurement.

When the input signal meets the requirements, use one of the **Copy** buttons (📄) to transfer the correct value to the numeric field. Alternatively, you can manually enter the value into the numeric field.

To finalize the trim, continue following the instructions displayed on the MC6-WS screen.



Note: Some HART instrument manuals and user interfaces incorrectly use the term *calibration* when they actually refer to a trim procedure.

Be cautious during the trimming procedure and closely follow the instructions in the instrument's user manual. Skipping any step may result in an unsuccessful trim.

Trimming a Fieldbus Instrument

Trimming a **FOUNDATION Fieldbus H1** or **Profibus PA** instrument can be started from the **Documenting Calibrator**, provided the relevant communicator option is installed and the parameter is trimmable.




Figure 148: Context-sensitive menu in Documenting Calibrator – calibrating a fieldbus instrument

The **Start Trimming** menu option opens a window similar to the [Figure 149: Fieldbus instrument Trim window example](#). The list of Blocks and Parameters displayed depends on instrument's Device Description file. The lower part of the window will display channels showing the instrument's input (1) and output (2) readings.

Figure 149: Fieldbus instrument Trim window example

Refer to the instrument's user manual for detailed information on how the trim procedure progresses. Typically, you first set the **Mode Block's** Target to OOS (Out Of Service) and then proceed to edit the other data.

The actual trim is performed by tapping the **Trim 0 %** or **Trim 100 %** values after a valid input signal is generated, simulated or measured. When the input signal meets the requirements, use one of the **Copy** buttons (📄) to transfer the correct value to the numeric field. Alternatively, you can manually enter the value into the numeric field.

To finalize the trim, continue following the instructions provided in the instrument's user manual.



Note: Some fieldbus instrument manuals and user interfaces incorrectly use the term *calibration* when they actually refer to a trim procedure.

Be cautious during the trimming procedure and closely follow the instructions in the instrument's user manual. Skipping any step may result in an unsuccessful trim.

Advanced Features

Tools

Certain subwindows include a **Tools** button () . Some tools are intended for measurements only, while others are designed for generations and simulations only.




Figure 150: Tools (Calibrator user interface mode view)



Note: The available tools also depend on the selected Quantity and Function. For example, switches offer only a limited number of tools.



Note: Several tools include a **Stop** button () in the pop-up window where the tool is configured. To stop a function, such as Damping, open its configuration window and tap the **Stop** button. This action restores the function's default settings.



Note: Changing the Quantity of a subwindow resets all tools to their default configurations, except for the Additional Info settings, which remain unchanged.



Tip: Calibrator user interface mode: Additional Info fields with black text can be zeroed "on the fly". Zeroing options are available in the context-sensitive menu of the Additional Info window.

Tool	Description	Available in
Scaling 	Any signal can be scaled provided the conversion is known. When Scaling is active, it is indicated by a triangle next to the unit. The true measurement value is displayed in the additional info row at the bottom of the subwindow.	✓ Measurements ✓ Generations/Simulations
		User Interface Modes
		✗ Meter ✓ Calibrator ✓ Documenting Calibrator ¹ ✓ Data Logger
Alarm 	Four Alarm limits can be assigned to main measurements: high, low, high change rate and low change rate. Active alarms are displayed above the main measurement. When an alarm limit is exceeded, a warning signal is heard. A button for acknowledging the alarm appears when necessary.	✓ Measurements ✗ Generations/Simulations
		User Interface Modes
		✗ Meter ✓ Calibrator ✗ Documenting Calibrator ✗ Data Logger

¹ Scaled units are not supported in CMX or LOGiCAL.

Tool	Description	Available in
Leak / Stability Test	A Leak / Stability Test can be assigned to main measurements. This test evaluates the leak or stability of, for example, a pressure measurement system. In the Leak / Stability Test configuration window, enter the Test time and start recording. If needed use the " +30 sec " button to extend the test time.	✓ Measurements ✗ Generations/ Simulations
		User Interface Modes
		✗ Meter ✓ Calibrator ✓ Documenting Calibrator ✓ Data Logger
Damping 	Damping can be activated when a measurement signal contains unwanted noise. Select one of the available options. When damping is used, a funnel icon appears to the left of the main measurement. When damping is active, the following symbol is shown above the unit button: 	✓ Measurements ✗ Generations/ Simulations
		User Interface Modes
		✗ Meter ✓ Calibrator ✓ Documenting Calibrator ✓ Data Logger
Resolution 	The Resolution of any signal can be increased or decreased. Changes in resolution are shown in the subwindow. For example, ".-2" means two fewer decimal places.	✓ Measurements ✓ Generations/ Simulations
		User Interface Modes
		✗ Meter ✓ Calibrator ✓ Documenting Calibrator ✓ Data Logger

Tool	Description	Available in
Ramp 	The Ramp tool opens a window that allows you to define a ramp function for the generated or simulated signal.	✗ Measurements ✓ Generations/ Simulations
		User Interface Modes
		✗ Meter ✓ Calibrator ✗ Documenting Calibrator ✓ Data Logger
Step 	The Step tool allows you to define a step function for generated or simulated signals. It enables the signal to increase or decrease in a predefined manner and provide the signal for a fixed duration. This feature is particularly useful when documenting data manually. The step time option specifies the delay time, which begins after the stability criteria have been met. For more information see chapter User-Defined Steps/Calibration Points . ²	✗ Measurements ✓ Generations/ Simulations
		User Interface Modes
		✗ Meter ✓ Calibrator ✗ Documenting Calibrator ✓ Data Logger

² When using the Step tool I for temperature generation, it is recommended to activate the tool's stability check to ensure that the temperature has stabilized before moving to the next step.

Tool	Description	Available in
Additional Info 	With Additional Info tool you can add additional information fields at the bottom of a subwindow. The available fields depend on the quantity and settings. Up to four fields can be added to each subwindow. The settings for the additional information rows are saved for future use.	✓ Measurements ✓ Generations/Simulations
		User Interface Modes ✗ Meter ✓ Calibrator ✗ Documenting Calibrator ✗ Data Logger
Quick Access Buttons 	Quick Access Buttons tool opens a window where you can define five shortcuts for user-defined generation or simulation values. These Quick Access shortcuts appear at the bottom of the subwindow, using the space reserved for possible Additional Info data.	✗ Measurements ✓ Generations/Simulations
		User Interface Modes ✗ Meter ✓ Calibrator ✗ Documenting Calibrator ✗ Data Logger
Function Info 	✓ Measurements ✓ Generations/Simulations Function Info button opens a pop-up window with information about the current function, including measurement range, calibration date and other relevant details.	✓ Measurements ✓ Generations/Simulations
		User Interface Modes ✗ Meter ✓ Calibrator ✓ Documenting Calibrator ✓ Data Logger


User-Defined Transfer Functions

Transfer Functions are available in the **Scaling** Tool found in the Calibrator, Data Logger and in the **Instrument Function Related Data** configuration page in the Documenting Calibrator mode.

When creating or selecting a user-defined transfer function, tap on the **Transfer Function** button and navigate to the **User Transfer Function** page.


The configuration consists of two (or more) pages, as shown in the figures below. The first page is for general definitions, and the second page is for

entering known transfer function points. If you enter more points than can be displayed on one page, an additional page is automatically added.



The screenshot shows the 'Transfer Function' configuration page. It has a title bar with a home icon, a menu icon, the title 'Transfer Function', and a close button (red X). The main area contains four sections: 'Transfer Function Name' with a text input field; 'Input Data Entry Range (Pa)' with two input fields showing '80000' (0%) and '120000' (100%); 'Output Data Entry Range ()' with two input fields showing '0' (0%) and '1' (100%); and 'Notes' with a text area. On the right side, there are navigation buttons: an up arrow, a '1 / 2' indicator, a down arrow, and a green checkmark button at the bottom right.

Figure 151: Transfer Function configuration page – general definitions



The screenshot shows the 'Transfer Function' configuration page for entering points. It has the same title bar as Figure 151. The main area is a table with two columns: 'Input (bar)' and 'Output (μA)'. There are six rows. The first row has a grey button with '1.', '0.8', and '0'. The second row has a grey button with '2.', '1', and '0.4999999'. The third row has a grey button with '3.', '2', and '3'. The fourth row has a grey button with '4.', '3', and '5.5'. The fifth row has a grey button with '5.', '4', and '8'. The sixth row has a grey button with '6.', 'Tap to Edit...', and 'Tap to Edit...'. On the right side, there are navigation buttons: an up arrow, a '2 / 2' indicator, a down arrow, and a green checkmark button at the bottom right.

	Input (bar)	Output (μA)
1.	0.8	0
2.	1	0.4999999
3.	2	3
4.	3	5.5
5.	4	8
6.	Tap to Edit...	Tap to Edit...

Figure 152: Transfer Function configuration page – transfer function points

When entering transfer function points, please follow these rules:

- The first point is always pre-entered and cannot be edited. It represents the 0 % values of the range.
- Points must be entered in increasing order.
- The last point must be equal to or greater than the 100 % value of the range.

Additionally:

- The row number acts as a button. Click it to open a window where you can delete the current point or add a new row either before or after the current point.
- Added points are assigned default values, which are the averages of the points before and after them.

User-Defined Steps/Calibration Points

User-defined steps can be accessed through the **Step** tool in the Calibrator and Data Logger user interface modes. The **Step** tool opens a window to define a step function for the generated or simulated signal. User-defined calibration points are available in the [Calibration Procedure Related Data](#) configuration page in the **Documenting Calibrator** mode.

When creating or selecting user-defined steps, use the **Step Definition** button.

Figure 153: User-defined steps – Step definition button

For user-defined calibration points, use the **Calibration Points** button. In the opened window, navigate to **User Test Points** page. The configuration consists of two (or more) pages, as shown in the figures below. The first page is for general definitions, and the second page is for entering test points. If you enter more points than can be displayed on one page, an additional page is automatically added.

User Test Points

Set Name

Point Data Entry Range (°C)

-200 0% ... 850 100%

Notes

1 / 2

Figure 154: User Test Points – general definitions

User Test Points

#	Point Data (°C)	≈%
1.	-200	0%
2.	0	19%
3.	200	38%
4.	400	57%
5.	Tap to Edit...	

2 / 2

Figure 155: User Test Points – steps/calibration points

There are no specific rules regarding the values you are allowed to enter. They may be outside the predefined point data entry range and can be input in any order.

Additionally:

- The row number acts as a button. Click it to open a window where you can delete the current point or add a new row either before or after the current point.
- Added points are assigned default values, which are the averages of the points before and after them.

User Sensors

MC6-WS includes a wide selection of pre-configured standard Platinum Resistance Temperature (PRT) type RTD sensors. These are available whenever **RTD Temperature** is selected as the Quantity. If correction coefficients are required for a specific sensor, you can create a User Sensor. Further instructions are provided in chapter [Creating a New User Sensor](#).

When a temperature sensor with a built-in memory chip is connected to the R2 connector, the calibrator automatically recognizes the sensor and can read ITS-90 correction coefficients from the memory, provided they were added by the calibration laboratory. Using Beamex RPRT, IPRT, or SIRT sensors calibrated in Beamex calibration laboratories ensures that the correction coefficients are stored and ready to use.




Figure 156: Sensor with built-in memory chip automatically recognized, example

If the sensor is not recognized, verify that the following conditions are met:

- The sensor is connected to the **R2 connector** (R1 and R3 terminals do not support smart sensor functionality).
- No adapter cable is used between the calibrator and the sensor's own LEMO connector.
- The sensor is equipped with a built-in memory chip:
 - Beamex IPRT sensors must have a serial number starting with **33025 or higher**.
 - Beamex SIRT sensors must have a serial number starting with **25 or higher**.
- The calibrator firmware version is **5.20 or later**.

Creating a New User Sensor



Note: Although custom sensors can be created and maintained in the MC6-WS, it is strongly recommended to define and manage user sensors (including correction coefficients) in CMX or LOGiCAL. This ensures centralized maintenance and availability for all compatible calibrators supporting the sensors.

You can create a new User Sensor whenever **RTD Temperature** is selected as the Quantity. To create a new User Sensor:

1. Press the button with sensor name.
2. Go to the second page of the User Sensor window.
3. Tap **Create New** button (.
4. Use the sensor's data sheet and calibration certificate to fill in the required details:
 - Sensor name
 - Serial number
 - Calculation formula and correction coefficients
 - Temperature range
 - Manufacturer and model
 - Calibration date

Make sure to select the correct Sensor Calculation Formula. It defines which settings and fields are available on the configuration pages. The calculation formula and correction coefficients can be found on the sensor's calibration certificate. For more details about the available calculation formulas and their use, see chapters [Callendar-Van Dusen Formula](#), [ITS-90](#), and [Factor](#).





Figure 157: Sensor Calculation Formula options



Note: For more detailed information about sensor calculation formulas, refer to literature related on calibrating Platinum Resistance Temperature (PRT) sensors.

When a temperature sensor with a memory chip is connected to the R2 connector, the calibrator automatically recognizes it and displays a pop-up window with the sensor information. Press **Create New** button (📄) to create a new User Sensor. Sensor data will be automatically populated into the correct fields. Review all pre-populated data and provide any missing information.

Figure 158: User Sensor configuration window, first page example




The image shows a 'User Sensor' configuration window with a green header bar. The window contains four input fields: 'Manufacturer' with the value 'Beamex Oy Ab', 'Model' with 'RPRT-660', 'Serial Number' with '09410', and 'Calibration Date' with '27-03-2025'. On the right side, there are navigation buttons: a red 'X' at the top, a blue up arrow, a '2 / 5' indicator, a blue down arrow, and a green checkmark at the bottom.

Figure 159: User Sensor configuration window, second page example

Using User Sensor

User Sensors are available for RTD Temperature input or output in any user interface mode. When a user sensor is in use, the sensor button shows a warning symbol (Δ) together with the name of the user sensor.



The image shows the 'Calibrator' interface with a green header bar. The header includes a home icon, the title 'Calibrator', the time '09:02', and a battery icon showing '2:03'. Below the header are three buttons: 'RTD', 'R2: Measurement', and a button with a warning symbol (Δ) and the text 'RPRT-660 - 09410'. The main display shows a large temperature reading '21.88' followed by a temperature unit button '°C'. At the bottom, there are three buttons: a wrench icon, a button with the Greek letter Ω and the value '108.696', and a button with '2 σ ' and '0.02'.

Figure 160: Example of a User Sensor in Calibrator mode



Note: Deleting a user sensor will stop any ongoing measurement, generation, or simulation that is using it.

Updating User Sensor Data

After the sensor has been recalibrated and the coefficients have changed, the User Sensor data saved in the calibrator needs to be updated. You can access Update mode the same way as when creating a new sensor. Update the coefficients according to the latest calibration certificate and save using the **Accept** button (✓). If a sensor has a built-in memory chip with updated correction coefficients from the calibration laboratory, these can be read directly from the sensor. Connect the sensor and press the **Settings** button in the pop-up window (which replaces the Create icon if the sensor is already stored). Confirm the values with the calibration certificate and save the updated data using the **Accept** button (✓).



Note: If calibration results for the User Sensor have been saved in the Documenting Calibrator and the correction coefficients are updated, the new coefficients will also apply to existing calibration results. Always transfer the results to the calibration management software or save them using other means before updating the sensor coefficients.

You can also edit sensor data directly in the calibrator and save it to the sensor's memory. This may be useful, for example, when recalibrating a sensor in a calibration laboratory that cannot write new coefficients to the sensor's memory. Attributes that can be updated include the calculation formula, correction coefficients, temperature range, and calibration date. Sensor name, manufacturer, model, and serial number cannot be changed.

After updating the User Sensor data, press the **Accept** button (✓) to save it. Any changes written to the sensor's memory must be confirmed with the calibrator's adjustment PIN code.



Note: When a sensor is connected, saving the User Sensor data applies the updates to both the calibrator and the sensor. The calibrator will request the adjustment PIN code before saving.

Callendar-Van Dusen Formula

When you select **CvD RTD (R_0 , A, B, C)** sensor calculation formula, you can configure the sensor's coefficients according to the Callendar–Van Dusen standard.

Figure 161: Constant and coefficients example for Callendar-Van Dusen

The Callendar-Van Dusen formula for PRTs can be defined using one of two equations, each with its own set of coefficients: A, B and C or α (alpha), δ (delta), and β (beta). In both cases, the R_0 constant is also required.

MC6-WS supports only the equation using coefficients A, B and C only. If your PRT's calibration certificate provides coefficients α , δ and β , use the following equations to convert them to A, B and C:

$$A = \alpha \cdot \left(1 + \frac{\delta}{100}\right) \quad B = \frac{-\alpha \cdot \delta}{10^4} \quad C_{T<0} = \frac{-\alpha \cdot \beta}{10^8}$$

Figure 162: Callendar-Van Dusen – equations for converting coefficients

ITS-90

The ITS-90 (International Temperature Scale of 1990) is a standard used for high-accuracy temperature measurements and calibration of precision thermometers.

When you select the **ITS-90 PRT (R tpw,...)** sensor calculation formula, you can configure the sensor using the R tpw constant. You can also enter one or more deviation coefficients (a_x , b_x , ...), where x typically ranges from 4 to 11, depending on the deviation formula used in the calibration.

If the x identifiers are missing from the coefficients in your calibration certificate, refer to the table below to identify which coefficients have been provided.



Note: The definitions of coefficient notations for the ITS-90 subranges are provided in the NIST Technical Note 1265, *Guidelines For Realizing the International Temperature Scale of 1990*.

Calibration ranges, corresponding coefficients and examples of calibration points:

Calibration Ranges [*]	Corresponding Coefficients	Example of fixed calibration points [#] , °C				
Negative (sub-)ranges:						
-189 ... 0 °C	a₄, b₄	-189.3442,	-38.8344,	0.01		
-38 ... 30 °C	a₅, b₅ ^(†)	-38.8344,	0.01,	29.7666		
Positive (sub-)ranges:						
0 ... 30 °C	a₁₁	0.01,	29.7666			
-38 ... 30 °C	a₅, b₅ ^(*)	-38.8344,	0.01,	29.7666		
0 ... 157 °C	a₁₀	0.01,	29.7666,	156.5985		
0 ... 232 °C	a₉, b₉	0.01,	156.5985,	231.928		
0 ... 420 °C	a₈, b₈	0.01,	231.928,	419.527		
0 ... 660 °C	a₇, b₇, c₇	0.01,	231.928,	419.527,	660.323	
0 ... 962 °C	a₆, b₆, c₆, d	0.01,	231.928,	419.527,	660.323,	961.78

^{*)} The range limits in the list are rounded and displayed as they appear in the MC6-WS user interface.

^{†)} Subrange 5 appears twice because it must be entered separately for both negative and positive temperature ranges.

^{#)} Not all calibration laboratories necessarily use the same reference points. The ones listed here are for guidance only.



Note: If your calibration certificate includes two sets of coefficients—one for zero current and another for 1 mA current—enter the latter one into the MC6-WS calibrator.

When you select the ITS-90 PRT (R t_{pw},...) sensor calculation formula, the **Sensor Range** entered on the first configuration page determines how many additional **User Sensor** pages are added to the MC6-WS. If the range includes temperatures below zero, the total number of configuration pages will be four:

- **The first page** contains the general settings.
- **The second page** is used to enter the **R t_{pw}** constant value.
- **The third page** allows you to select the deviation formula for the negative temperature subrange and enter the corresponding coefficients (a₄ and b₄ or a₅ and b₅).

- **The fourth page** is for selecting the deviation formula for the positive temperature subrange and entering the relevant coefficients (a_5 , a_6 , a_7 ... etc.).



Note: When the calibration does not include a negative subrange, the third page mentioned above is excluded, and the total number of configuration pages is three.

The screenshot shows a software interface titled "User Sensor". It features a "Deviation Formula" section with a text box containing "0 ... 660 °C: a_7 , b_7 , c_7 ". Below this are three input fields labeled "a", "b", and "c". The values entered are $-2.122E-4$, $-1.407E-4$, and $5.059E-5$ respectively. On the right side, there are navigation buttons: a red "X" at the top, a blue up arrow, a "5 / 5" indicator, a blue down arrow, and a green checkmark at the bottom.

Figure 163: Coefficients example for ITS-90

Factor

The third method for customizing an RTD sensor (not just PRTs but all types of RTDs) is by using the **Factor**. This approach is suitable for sensors that show a consistent relative error across the entire span, effectively behaving as if there is an offset in their output.

To configure a User Sensor using the Factor, follow these steps:

1. Select a standard RTD **Sensor Type** from the available options.
2. Input a Factor that offsets the standard temperature curve to match your sensor's characteristics.
3. Use a simple reference example. One practical method is to select a standard RTD sensor with a resistance of 1 ohm at 0 °C, such as Pt1.
4. Enter your sensor's actual resistance at 0 °C as the Factor value.




Figure 164: Configuration page example for Factor

Check Sensor Conversion


You can test sensors in the window that displays both pre-entered and custom RTD sensors.

To access **Check Sensor Conversion** feature, open the context-sensitive menu in the User Sensor configuration page.

The [Figure 165: Check Sensor Conversion configuration page](#) shows the first of the **Check Sensor Conversion** pages. This page allows you to select a sensor, choose the unit to be used, and test a single point. This feature is especially useful when you have entered coefficients for a custom sensor and want to verify that they were entered correctly.

To test, enter a temperature value from the calibration certificate and check whether the calculated resistance in the MC6-WS matches the value on the certificate.

Enter, e.g. a temperature that is in the calibration certificate and check if the calculated resistance in MC6-WS is the same as on the calibration certificate. If the values match, the coefficients have been entered correctly. If not, review and correct the coefficients you entered.



The image shows a software window titled "Check Sensor Conversion" with a red close button in the top right corner. The window contains the following fields and controls:

- Sensor Type:** A button labeled "Pt 100 258497".
- Unit:** A button labeled "°C".
- Calculate (°C):** A text input field containing the value "0".
- Calculate (Ω):** A text input field containing the value "100".
- A double-headed arrow (↔) is positioned between the "Calculate (°C)" and "Calculate (Ω)" fields.
- Table Step Size (°C):** A text input field containing the value "20".
- Table Step Size (Ω):** A text input field containing the value "0.1".
- On the right side, there are two buttons: an "Up" arrow button and a "Down" arrow button.
- Between these two buttons is a small label "1 / 3".

Figure 165: Check Sensor Conversion configuration page

The lower part of the first page allows you to define step sizes for the tables shown on the second and third pages. These tables display the correlation between temperature and resistance (and vice versa).

Controller Communication

Using MC6-WS together with a pressure controller or a temperature dry block enables fully automated calibration of various pressure and temperature instruments. Optional communication drivers are available for a range of Beamex and third-party pressure controllers and temperature dry blocks. For a complete list of available communication drivers, please contact Beamex.

To view the installed options on your calibrator navigate to **Settings > About**.

Enabling Communication with the Controller

The MC6-WS does not automatically recognize an external controller. To pair the devices, you must configure the controller communication settings. Once the units are paired, communication is plug-and-play when connected to the calibrator. A maximum of four controllers can be assigned to Controller Presets channels.




Figure 166: Controller Preset example

To set up the connection between the calibrator and the external controller:

1. Connect the devices using a suitable communication cable. Use any available USB-A port on the calibrator.
2. Power on both the calibrator and the controller.
3. From MC6-WS **Home View**, go to **Settings > Controller Presets**.
4. Specify the following parameters:
 - **Connection Interface:** Displays the connected controllers and their serial numbers. Select the unit you want to pair.
 - **Controller Type:** Choose the appropriate type for the connected controller. The list of options varies according to the controller drivers installed. Each communication driver is a separate option that must be purchased individually.
 - **Control Mode** (Shut off or Continuous): Determines whether pressure adjustment stops at the setpoint or continues after reaching it.

Once an external controller is connected and configured, it is also available in the MC6-WS Port/Function selection when Pressure or Temperature is selected as the input quantity.




Figure 167: Pressure Port / Function list with controllers available

The context-sensitive menu in the **Controller Preset** window includes additional tools for configuring communication settings. The additional settings in the context-sensitive menu can be configured independently for each preset.

The Controller Preset context-sensitive menu also provides access to the **Communication Log**. In the Communication Log window, you can choose the log format: either text-format or binary-format.



Note: If you experience communication issues, check the communication settings of the connected controller. These settings may have been modified from the default values. The MC6-WS calibrator always uses the default values of the controller.



Note: When connecting a Beamex FB or MB Temperature Dry Block, make sure both devices are powered on before connecting the communication cable and starting communication between them.

Calibration Methods with External Controllers

There are three alternative methods of using an external controller with the MC6-WS calibrator:

- **Controlled and Measured** (full use)

In Controller mode, the calibrator controls an external controller to set the calibration points, and the controller's internal measurement is used to measure the reference signal. Controllers without internal measurement capability, such as the Beamex ePG, cannot use this mode. For pressure controllers, select this mode with Quantity set to Pressure. For temperature dry blocks, select this mode with Quantity set to Temperature.



Note: This method is available in the Calibrator, Documenting Calibrator and Data Logger modes. In CMX and LOGiCAL Calibration Management Software, it corresponds to selecting the Controlled and Measured Input method.

- **Controlled**

In Controlled mode, the calibrator manages an external controller to set the calibration points, while the input signal generated is measured by the calibrator. The measurement channel is chosen in the Input Port / Function. For pressure controllers, select this mode with Quantity set to Pressure. For temperature dry blocks, select RTD Temperature or TC Temperature as the Quantity, depending on the reference measurement type.



Note: This method is available only in the Documenting Calibrator mode. In CMX and LOGiCAL, it corresponds to selecting Controlled Input method.




Figure 168: Instrument Input settings with Controlled method selected

- **Measured**

In CMX and LOGiCAL, you can also choose Measured as the input method. When using this method for pressure or temperature quantities, the reference signal must be generated by an external source that the calibrator does not control, such as a hand pump for pressure or an ice bath for temperature.



Note: If a pressure controller is internally connected to the MC6-WS, the USB port on the front panel is not required.

Wireless Communication

The optional Wireless Communication feature enables Bluetooth data transfer between the MC6-WS and Beamex Calibration Management Software. This functionality eliminates the need for USB cable, simplifying the communication.

Connect the Bluetooth adapter to the calibrator's USB-A port, enable Bluetooth communication in the calibrator's settings, and pair it with a PC. Data can then be transferred between the calibrator and the Beamex Sync client, the CMX Send/Receive window, or the CWSI client. For more information, see chapter [Enabling Communication with a Client Device](#).

Detailed system requirements can be found in chapter [Requirements](#).

Connection Security

Beamex Wireless Communication uses Bluetooth Low Energy (BLE) technology. We ensure security by authenticating the pairing process and encrypting connections with 128-bit AES encryption. This setup aligns with Security Mode 1, Level 3, providing robust protection.

Requirements

For Wireless Communication to function, the following criteria must be met:

- ASUS USB Bluetooth adapter provided by Beamex



Note: If the Beamex-provided ASUS USB Bluetooth adapter is not approved in your country, you may use a locally sourced micro Bluetooth adapter that meets the following requirements:

- Supports Bluetooth Low Energy (BLE).
- Compatible with Bluetooth 4.2 or higher.
- Maximum height: 8 mm / 0.315".
- Interface: USB-A.



Note: It is recommended to use adapters from known manufacturers with all required approvals, such as CE/UKCA.

- Computer or Smart device with Bluetooth Low Energy and support for at least Bluetooth 4.2. From this point onward, referred to as the **Client device**.




Note: CMX Calibration Management Software: Bluetooth is supported in version 2.15.1 or later.


Enabling Communication with a Client Device

To enable Wireless Communication between an MC6-WS calibrator and a Client device, you must first pair them. Follow the steps below to pair your MC6-WS with the Client device:


1. Plug the USB Bluetooth adapter into your MC6-WS.
2. Go to **Home View > Settings > Wireless**. The Wireless button should be visible and accessible on the second page of the Settings. If it is not visible, check the [Troubleshooting](#) chapter.




3. Turn Bluetooth on.




4. Search for available Bluetooth devices on the Client device.




5. Select your calibrator.



6. Check that the passcode displayed on both the MC6-WS and the Client device matches, then press **Pair** / **Connect**.



7. After successful pairing, your MC6-WS will appear in the Beamex Calibration Management Software. See the example below (CMX Calibration Management Software).



Tip: If you need to swap the adapter between calibrator units, first unpair the USB Bluetooth adapter from both the calibrator and the Client device to enable new pairing. Note, that unpairing on the calibrator is only possible when Bluetooth is turned on.

Information Window

Wireless Communication Information window can be accessed by pressing the **Info** button (.

The Information window displays the main connection parameters, such as the host's and client's MAC addresses and names. For a detailed description and examples of these parameters, see the picture and the explanation table below.




Figure 169: Information window example

Table 7: Information window - parameters and their descriptions

Address	MAC address of the host device
Name	Name of the host device, formatted as: " <i>Device model: Serial number Owner</i> "
State	Connection status as follows: • <i>Disconnected</i> – the devices are not connected • <i>Connected - not paired</i> – the devices are connected but not paired • <i>Connected - paired</i> – the devices are connected and successfully paired
Client Name	Name of the client device
Client Address	MAC address of the client device
Received Signal Strength	Strength of the received radio signal
Transmit Power Level	Level of transmit power, automatically controlled by the Bluetooth protocol

Troubleshooting

The Wireless button is greyed out.	
POSSIBLE REASON	SOLUTION
The Wireless Communication option has not been installed.	Contact Beamex Sales to request an upgrade.
No compatible Bluetooth adapter is present.	Check that the adapter meets the requirements, or insert a Beamex-recommended adapter.

It is not possible to pair or establish the connection.	
POSSIBLE REASON	SOLUTION
The USB Bluetooth adapter was swapped between different calibrators.	Unpair the USB Bluetooth adapter from both the calibrator and the Client device to enable new pairing. Note that unpairing on the calibrator is only possible when Bluetooth is turned on.

MC6-WS is not discoverable, or the wireless connection process is not functioning correctly.	
POSSIBLE REASON	SOLUTION
	Turn Bluetooth off and then back on to potentially resolve the issue

Connection is lost.	
POSSIBLE REASON	SOLUTION
The environment is noisy.	Try changing the Connection setting to Maximum Range (see picture below). It offers lower speed but better coverage.
There is a long distance between Client device and the calibrator.	




Figure 170: Connection, Maximum Range

Settings

The **Settings** user interface mode allows you to configure MC6-WS according to your needs.




Figure 171: Home view, Settings user interface mode

The following settings are available for configuration:

- **Language** – Allows you to select the user interface language.
- **About** – Provides access to information such as the serial number, firmware version, installed modules and options.
- **Power Management** – Lets you define auto-off delays and adjust display brightness.
- **Sound Volumes** – Allows you to set volume levels for different sounds emitted by the calibrator.

- **Date & Time** – Lets you configure the date, time, time zone, and Daylight Saving Time.



Note: If the Mobile Security Plus option is enabled, certain settings can only be changed with restrictions:

- Changing Date & Time and Regional Settings requires admin credentials.
- The default PIN code 2010 for changing module data is disabled, and a device-specific code must be used instead.
- Factory reset cannot be performed.

Additional details are available in chapter [Mobile Security Plus Option](#).



Note: The calibrator automatically synchronizes its date and time with the computer during communication with the calibration management software, ensuring correct time settings.

- **Regional Settings** – Used to define default values for the temperature unit and scale, set the local net frequency, and select the barometric pressure unit.



Note: Changing Regional Settings requires reselecting the Port/Function for the changes to take effect.

- **Owner** – Lets you enter owner information, which is displayed in the Home View.
- **Controller Presets** – Gives you access to preset configurations when controller communication option is installed. Further information can be found in chapter [Controller Communication](#).
- **Maintenance** – Allows you to set the calibration date, update the firmware, align the touch screen, perform a factory reset, and delete usage data.



Note: The PIN code for changing the module data is **2010**. The PIN code for MC6-WS adjustment is device-specific and was provided with the MC6-WS calibrator. More information is available in chapter [Recalibrating and Adjusting MC6-WS](#).



Note: Use a stylus when aligning the touch screen.

- **Documenting Calibrator** – Contains settings related to instrument calibration, such as enabling “Save as Both,” which allows a single calibration run to be saved as both As Found and As Left.
- **HART, FOUNDATION Fieldbus H1 and Profibus PA** – Provides access to settings for defining communication parameters of smart instruments. For further explanation and descriptions of the available parameters, refer to chapters [Communicator](#) and [Working With Smart Instruments](#).
- **Wireless** – If enabled, allows you to turn on Bluetooth and check the Connection Status.



Tip: You can **Recall Factory Settings** from the context-sensitive menu in several subsettings, such as Documenting Calibrator settings or HART settings.

Maintenance

Beamex calibrators are designed for long service life and to be as easy as possible to repair, maintain, and upgrade. The capabilities of the MC6-WS can be expanded with software and hardware options. For available options, see chapters [Software Options](#) and [Pressure Modules](#).

After purchasing a software option for an existing calibrator, Beamex will create and deliver an option file (.opt) to you. The software options can be installed using the free **MC6 Option Installer** PC tool, see section [Available PC Tools](#). All hardware options must be installed by Beamex.

The **Beamex Care Plan** is the easiest way to maintain the accuracy and reliability of your MC6-WS throughout its lifetime. It is a service contract that covers annual recalibration, repairs (including accidental damage), a simplified service return process, and more. For details, visit the <https://www.beamex.com/services/service-plans/>.



Warning: Repair of the MC6-WS must only be performed by an authorized partner. There are no user-replaceable parts within the calibrator, except the battery pack that has its own compartment on the back side of the calibrator. Do not open the enclosure!

Accessories and spare parts, such as chargers, cases, and communication cables, can be ordered from the [Beamex Webshop](#).

Cleaning Instructions



Note: Before using any cleaning or decontamination method not officially recommended by Beamex, consult an authorised service centre to ensure the method will not damage the equipment.

If MC6-WS requires cleaning, use a cloth soaked in a mild solution of tall oil soap (pine soap) or a common liquid dish soap. After wiping, wait a few minutes before cleaning the surface again with a cloth dampened with clean water. Never use strong detergents.



Note: To clean the display, use a microfiber cloth. If needed, apply a mild detergent and remove it thoroughly afterwards.



Caution: Isopropanol-based cleaning spray is not recommended for cleaning the MC6-WS, as it may damage the surfaces. However, it can be used to clean the pressure connectors.

Firmware Update

Beamex products are constantly evolving. Firmware updates are regularly published to introduce new features and enhance performance.



Note: To check the current firmware version of your calibrator go to **Settings > About** and compare it with the latest release to see whether an update is required.

Firmware update files and instruction can be found under the Resources tab on the [MC6-WS page](#) on the Beamex website. Save the firmware update file to a USB flash drive, then install it on the calibrator.

The calibrator firmware can be updated through the user interface by navigating to **Settings > Maintenance > Update Firmware**.




Figure 172: Update Firmware button in Settings user interface mode



Note: Updating the firmware does not erase the time, date, or any user-entered data (such as instruments, calibration results, or data logs).

Replacing the Battery Pack



Warning: Make sure to read and understand all warnings in chapter [Warnings Concerning the Lithium-ion Battery Pack](#).



Warning: Using an unauthorized battery pack may compromise the safety of the MC6-WS, posing a risk of fire or explosion. The use of non-approved battery packs will void the warranty.



Note: With time the capacity of the Lithium-ion batteries deteriorates and MC6-WS loses its time and date.

To remove or replace the Lithium-ion (Li-ion) battery pack, follow these steps:



Caution: Ensure both CENTRiCAL and MC6-WS are powered off.

Disconnect the mains cables from the wall outlet.

Unscrew the screws securing the module to the Instrument Panel (located at the corners of the front panel).

Remove the module from the Instrument Panel and disconnect any remaining connections between the MC6-WS and the Instrument Panel.

1. Remove the MC6-WS cover (see callout #1 in [Figure 173: Replacing the battery pack](#)) using a Torx T20 screwdriver.
2. The battery pack is located at the rear of the MC6-WS (see callout #2 in [Figure 173: Replacing the battery pack](#)).
3. Unplug the battery pack's connection cable (see callout #3 in [Figure 173: Replacing the battery pack](#)) and remove the battery pack.
4. Dispose of the battery pack according to local regulations. See chapter [Disposing the Battery Pack](#).
5. Insert the new battery pack into the slot and connect the cable to the circuit board.
6. Power on CENTRiCAL and the MC6-WS. Make sure that the MC6-WS is working correctly.

Before starting regular use, teach the MC6-WS the capacity of the new battery pack. Instructions can be found in chapter [Teaching the Battery](#).




Figure 173: Replacing the battery pack

Teaching the Battery

To ensure accurate battery readings, the calibrator must undergo a full battery cycle — this means charging it to 100%, discharging it completely to 0%, and then charging it back to 100% again without interruptions.

If the calibrator does not go through a full charge-discharge cycle, it may display incorrect capacity and charge level information.

To restore accurate readings, complete a full battery cycle, then teach the calibrator the new battery capacity by following these steps:



Note: Make sure the calibrator is powered on and running on battery power. Charger must not be connected. Make sure the calibrator is powered on and that the Main switch is turned off.

1. Go to **Settings > Power Management** and set the **Calibrator Auto-off Delay** value to 0.
2. Wait until the unit powers down due to an empty battery pack.
3. Charge the battery pack by switching the Main switch on.
4. Allow the battery pack to fully charge without interruptions. A plug icon (🔌) will appear on the display when charging is complete.



Note: If the battery is replaced by Beamex service, the teaching cycle is not required.

Recalibrating and Adjusting MC6-WS

Recalibrating the Calibrator

As with any test and measurement device, the MC6-WS must be recalibrated at regular intervals. Beamex recommends annual recalibrations to maintain optimal accuracy and reliability throughout the calibrator's lifetime.

The MC6-WS is a high-accuracy instrument and should only be recalibrated at laboratories capable of ensuring low measurement uncertainty. It is strongly recommended to use an ISO 17025-accredited laboratory with a certified quality management system. Recalibration through Beamex or a Beamex-authorized service center ensures the calibrator is cleaned, fully tested, updated with the latest firmware, and recalibrated in a facility that meets the calibrator's specifications.



Tip: When sending MC6-WS to Beamex for recalibration, there is no need to include the charger.



Note: When sending MC6-WS to another calibration laboratory for recalibration, include the portable MC6 Calibrator charger if possible.



Note: During the calibration procedure, disconnect the charger to avoid possible disturbances. Also, ensure MC6-WS batteries are fully charged.



Caution: If recalibrating MC6-WS on site while installed in CENTRICAL, ensure that both MC6-WS and CENTRICAL are properly grounded.

Before sending any equipment for recalibration or repair, submit a service or quotation request through the Beamex Service Portal at <https://services.beamex.com>.

Calibration and Adjustment Instructions

Detailed MC6-WS calibration and adjustment instructions are available for calibration laboratories. To request access, please submit a support request at

<https://support.beamex.com>. Beamex will verify the request before providing the instructions.

Changing Calibration Date and Interval

To change the calibration date and interval of the calibrator or its modules, go to **Settings > Maintenance > Change Module Data**. When prompted, enter the PIN code **2010**.

Once the correct PIN is entered, the **Change Module Data** window opens, allowing you to edit the calibration dates and intervals for all built-in modules and connected EXT External Pressure Modules.



Tip: To reset the recalibration notification, set a new calibration date or extend the calibration interval.



Note: If the **Mobile Security Plus** option is installed, the default PIN code **2010** is disabled. Use the unit-specific PIN code provided with the calibrator.

Adjusting the Calibrator

A calibration laboratory can adjust the calibrator modules by navigating to **Settings > Maintenance > Adjust Calibrator**. A PIN code entry window will appear. The adjustment PIN code is unit-specific and was shipped with your calibrator.

If the adjustment PIN is lost:

1. Submit a support request to Beamex at <https://support.beamex.com>.
2. Provide your calibrator's serial number and be prepared to verify your identity and ownership of the unit.
3. Beamex will perform the necessary verifications before providing the PIN code.

Preparing the MC6-WS for Service Returns

If you need to return the unit to the factory for any reason, contact Beamex first. Submit a service or quotation request through the Service Portal at <https://services.beamex.com>.

Before shipping your calibrator, review the instructions for service returns and Beamex policy on shipping equipment with Lithium-ion (Li-ion) batteries at <https://www.beamex.com/services/service-returns/>.



Note: Always check and follow all local regulations for shipping equipment with Lithium-ion (Li-ion) batteries.



Note: Do not ship equipment to Beamex without prior notice. Always contact Beamex first.



Note: Beamex recommends downloading and removing all saved calibration results from the MC6-WS before shipping. Use calibration management software to store your results permanently.

Place the MC6-WS in its original packaging as received upon delivery from Beamex. If the original packaging is not available, use 40 mm softeners on all sides to ensure safe delivery.

If you are using another service provider, follow Beamex packing instructions for service returns.

Resetting the Calibrator

There are two types of resets:

- **Reset/Restart:** Used if the calibrator becomes unresponsive. This reset does not erase any user-entered data.
- **Factory Reset:** Restores the calibrator to its original factory state. This reset erases all user-entered data, and the deleted data cannot be recovered.

To reset or restart the calibrator, press and hold the **Home** and **Enter** keys at the same time for 7 seconds.



Note: Resetting/restaring the MC6-WS affects its internal clock. After a reset, remember to check the date and time, and correct them if necessary. None of the saved data is affected by the reset. However, any open files may be lost.

To perform a Factory Reset, navigate to **Settings > Maintenance > Change Module Data** and enter the PIN code **926535**.



Note: Factory reset erases all user-entered data (such as instruments, calibration results, or data logs), and the deleted data cannot be recovered. Factory reset does not erase installed firmware updates, software options, or Device Descriptions.



Caution: Deleted data cannot be recovered.



Note: Factory reset cannot be performed if the calibrator has Mobile Security Plus option installed.

Installing and Uninstalling Modules in CENTRiCAL

Instructions for installing or uninstalling modules in CENTRiCAL can be found in the CENTRiCAL Workshop Calibration Solution user manual.



Note: If you install the MC6-WS into the CENTRiCAL Instrument Panel yourself, ensure that the MC6-WS and all its pressure modules are properly grounded.

Disposing of Waste Electrical and Electronic Equipment

Sustainability is a core component of the Beamex design philosophy. We want our customers to continue using their Beamex products for many years, so they are designed to have a long service life and to be as easy as possible to repair, maintain, and upgrade. This supports the circular economy and conserves valuable natural resources. The environmental management system used at Beamex is ISO 14001:2015 certified.

In the European Union (EU) and other regions with separate collection systems, waste electrical and electronic equipment (WEEE) is subject to specific regulations.

The **EU WEEE Directive 2012/19/EU** requires producers of electronic equipment to take responsibility for the collection, reuse, recycling, and proper treatment of WEEE placed on the EU market after August 13, 2005.

The directive aims to:

- Preserve, protect, and improve the quality of the environment
- Safeguard human health
- Conserve natural resources




Figure 174: Symbol for recycling of electrical and electronic equipment

The symbol presented in the figure above is engraved on the back of the product. It indicates that the product must be taken to an appropriate collection point for the recycling of electrical and electronic equipment.

By returning your calibrator to Beamex for recycling, you can ensure the calibrator is recycled in an environmentally safe and secure manner. The dismantle and disposal process is handled according to Beamex ISO 14001 Environmental management system. Beamex will provide a Certificate of Recycling that certifies that you are released from liability for materials.

For more detailed information about recycling this product, please contact Beamex or waste disposal service provider.

Disposing the Battery Pack

The MC6-WS contains a Lithium-ion (Li-ion) battery pack.



Warning: Used MC6-WS battery pack is considered hazardous waste. Always dispose of used batteries safely and according to local regulations.

To dispose of the MC6-WS battery pack, follow these steps:

1. First, discharge the battery pack by using the calibrator normally.
2. Then, remove the battery pack as described in chapter [Replacing the Battery Pack](#).



Warning: To avoid short-circuiting, insulate the terminals with adhesive tape.

3. Finally, place the battery pack in a fireproof container and dispose of it according to local regulations.



Warning: Do not crush, short-circuit, or incinerate battery under any circumstances.



Warning: Do not transport the battery pack intended for disposal as cargo or freight.

Statements

Disclaimer

Beamex has taken great care to ensure that this manual contains both accurate and comprehensive information. Notwithstanding the foregoing, the content of this manual is provided “as is” without any representations, warranties or guarantees of any kind, whether express or implied, in relation to the accuracy, completeness, adequacy, currency, quality, timeliness or fitness for a particular purpose of the content and information provided on this manual. The content of this manual is for general informational purposes only. To the extent permitted by law, Beamex shall not be liable for any direct, indirect, special, consequential or incidental loss or damage (including but not limited to damage for third parties and loss of use, loss of profit and loss of production) in relation with the use of this manual, even if Beamex has been advised of the possibility of such damages.

Beamex reserves the right to amend this manual at any time without prior notice. Furthermore, the products this manual describes are subject to change without prior notice due to Beamex’s continuous product development process.

Intellectual Property Rights

Copyright

The content of this manual is the property of Beamex Oy Ab and/or its subsidiaries and affiliates (referred hereinafter as Beamex). This manual and its content are protected by international copyright laws and all copyrights are retained by Beamex. All rights reserved. Reproduction, distribution, transfer or storage of the content presented in this manual, in whole or in part, is illegal and prohibited without the prior written consent of Beamex.

The Beamex MC6-WS is a product of Beamex and contains FCG SDC-625 technology. The FCG SDC-625 technology is owned by FieldComm Group (FCG), 9430 Research Blvd., Suite 1-120 Austin, Texas 78759, and may not be adopted, copied, reproduced, modified, licensed, sublicensed, sold or resold other than under license from FCG.

The Beamex MC6-WS contains licensed software which requires that its source code is available for you. Please contact Beamex to obtain it.

The Beamex MC6-WS is based in part on the FLTK project (<http://www.fltk.org>).

Trademarks

"Beamex", "Beamex MC6", "Beamex – World-Class Calibration Solutions" as well as the color combination of green and black as applied to the major part of the visible surfaces of a measurement device, are registered trademarks of Beamex Oy Ab.

No content provided in this manual should be interpreted as a permission or license to use Beamex trademarks. The use of Beamex trademarks without the approval and consent of Beamex is prohibited and violates trademark laws.

HART is a registered trademark of the FieldComm Group (FCG).

FOUNDATION Fieldbus is a registered trademark of FieldComm Group (FCG).

PROFIBUS is a trademark of PROFIBUS International.

Windows is a registered trademark of Microsoft Corporation.

All other trademarks or trade names mentioned in this manual are the property of their respective holders.

Index

A

About this manual.....	7
Active Device Descriptions.....	
Basic View.....	118, 122
Device Specific.....	118
Generic.....	118
Adjustment instructions.....	183
Auto-off feature.....	26
Automatic Acceptance.....	80

B

Battery level.....	25
Battery pack.....	
Charge.....	26
Dispose.....	187
Replace.....	181
Teach.....	182
Beamex.....	
Adjustment.....	183
Recalibration.....	179, 183
Repair.....	179
Service.....	184
Service Portal.....	179
Services.....	39
Buttons.....	19

C

Calibration.....	
Fail.....	82
Fieldbus instrument.....	141
Group.....	96
HART instrument.....	139
Input.....	70
Instrument Overview.....	77
Map smart instrument data.....	134
Output.....	70
Pass.....	82
Calibration Management Software.....	
CMX.....	37
LOGiCAL.....	37
Calibration Point Acceptance.....	80
Calibration process.....	70
Calibration results.....	
As Found.....	71
As Left.....	71
Combine with Previous Result.....	82
Delete.....	82, 86
History.....	85
Save.....	82
View.....	85
Calibration Results window.....	82

Calibrator.....	67
Callendar–Van Dusen.....	159
Certifications.....	9
Change controller during calibration.....	103
Charger.....	25, 26
Charging procedure.....	26
Charging status.....	25
Cleaning instructions.....	179
CMX.....	37
Communication protocol.....	
FOUNDATION Fieldbus H1.....	117
HART.....	117
PROFIBUS PA.....	117
Communicator.....	117
Connect external pressure module.....	44
Connections.....	
Reference Junction.....	62
Smart instrument.....	61
Thermocouple.....	62
Controller communication.....	164
Copyrights.....	189
Current generation.....	57
Current measurement.....	48
Customize mappings.....	
Device Model Defaults.....	135
Field mapping.....	135
Protocol Defaults.....	135

D

Data log.....	
Fieldbus instrument.....	141
HART instrument.....	139
Logging methods.....	112
Start.....	112
Triggers.....	108
Data log configuration.....	
Open.....	108
Save.....	108
Data log results.....	
Delete.....	113, 114
History.....	114
Save.....	113
View.....	114
Data Log Viewer.....	39, 115
Data Logger.....	108
Data Logger channel.....	108
Data management.....	24
DD file.....	118
Device Description file.....	118
Device Description Installer.....	39, 118
Disclaimer.....	189
Disconnect external pressure module.....	44
Display.....	25
Dispose battery pack.....	187

Disposing of Waste Electrical and Electronic Equipment.....	186
Documenting Calibrator.....	69

E

External controllers.....	
Communication log.....	164
Presets.....	164
External Pressure Modules.....	44

F

Factor.....	162
Factory hierarchy.....	72, 75
Fieldbus Configuration Viewer.....	39, 123
Fieldbus instrument.....	
Calibrate.....	141
Log data.....	141
Trim.....	145
Firmware update.....	
MC6-WS.....	180
Frequency generation.....	59
Frequency measurement.....	50

G

Generation.....	
Current.....	57
Frequency.....	59
Pulse.....	60
Voltage.....	58
Get Mapped Values.....	133
Group calibration.....	
Add to group.....	96
Cancel group.....	96
Create group.....	96
Remove from group.....	96
Group Calibration.....	
Settings.....	101
Group settings.....	101

H

Hardware overview.....	19
HART.....	
Sensitivity.....	131
Settings.....	131
HART instrument.....	
Calibrate.....	139
Log data.....	139
HART instruments.....	
Trim.....	143
Home View.....	29

I

Input method.....	
Keyed.....	70
Install and uninstall modules in CENTRiCAL..	186
Instrument.....	
Calibrate.....	78
Copy.....	77
Create.....	86
Delete.....	77
Move.....	77
Instrument data.....	
Configuration pages.....	86
Device.....	70, 95
Error limit.....	70, 94
Function.....	70, 88
Identification.....	70, 87
Input.....	70, 88
Output.....	70, 88
Position.....	70
Procedure.....	70, 92
Tag.....	70
Instrument List.....	72
Instrument Overview window.....	77
ITS-90.....	160

L

LOGiCAL.....	37
Loop supply.....	48
Loop supply voltage.....	
Sink mode.....	57
Loop supply voltage'.....	
Source mode.....	57

M

Maintenance.....	
Clean MC6-WS.....	179
Dispose battery pack.....	187
Dispose MC6-WS.....	186
Disposing of Waste Electrical and Electronic Equipment.....	186
Firmware update.....	180
Install and uninstall modules in CENTRiCAL.....	186
Pack MC6-WS.....	184
Recalibrate MC6-WS.....	183
Replace battery pack.....	181
Reset MC6-WS.....	185
Service.....	184
Teach battery.....	182
MC6-WS.....	
Accessories.....	39
Battery pack.....	25
Buttons.....	19
Certifications.....	9
Charger.....	25, 26

Clean.....	179
Dispose.....	186
Hardware overview.....	19
Pack.....	184
Ports and connectors.....	19
Power management.....	26
Pressure modules.....	21
Recalibrate.....	183
Reset.....	185
Safety.....	9
Service.....	184
Settings.....	176
Software options.....	38
Specifications.....	17
Terminals.....	19
Warnings.....	9
Measurement.....	
Current.....	48
Frequency.....	50
Pressure.....	41
Pulse counting.....	51
Resistance.....	45, 47
RTD.....	45
Switch sensing.....	53
Thermocouple.....	46
Voltage.....	49
Memory.....	24
Meter.....	65
Mobile Security Plus.....	106

O

Option Installer.....	39
-----------------------	----

P

Packing instructions.....	184
PC tools.....	
Data Log Viewer.....	39
Device Description Installer.....	39
Fieldbus Configuration Viewer.....	39
Option Installer.....	39
Remote Controller.....	39
Plant Structure.....	72
Plant Structure Level.....	75
Ports and connectors.....	19
Power management.....	26
Pressure measurement.....	41
Pressure modules.....	21
PRT sensors.....	
Check Sensor Conversion.....	163
Pulse counting.....	51
Pulse generation.....	60

R

Recalibrating instructions.....	183
---------------------------------	-----

Reference junction.....	46
Reference Junction connections.....	62
Reference Junction mode.....	
External.....	62
Fixed.....	62
Internal.....	62
Manual.....	62
Remote Controller.....	39
Replace battery pack.....	181
Resetting instructions.....	185
Resistance measurement.....	47
Resistance simulation.....	56
RTD measurement.....	45
RTD sensors.....	
Check Sensor Conversion.....	163
RTD simulation.....	54

S

Safety.....	
Precautions and warnings.....	10
Safety symbols.....	9
Sensor calculation formula.....	
Callendar-Van Dusen.....	159
Factor.....	162
ITS-90.....	160
Service.....	184
Settings.....	176
Simulation.....	
Resistance.....	56
RTD.....	54
Thermocouple.....	55
Smart instrument configuration.....	
Link to CMX.....	126
Manage.....	123
Open.....	123, 125
Print.....	123
Save.....	123, 124
View.....	123, 125
Smart instrument connections.....	61
Smart instrument parameter.....	
Editing.....	130
Smart instruments.....	
Get Mapped Values.....	133
List of found devices.....	132
Parameters.....	128
Supply voltage.....	131
Trimming.....	143
Value Parameter.....	128
Software options.....	
Communicator.....	38
Data Logger.....	38, 108
Mobile Security Plus.....	38, 106
Wireless communication.....	38, 168
Specifications.....	17
Supply voltage.....	48
Switch sensing.....	53

T

Teach battery.....	182
Terminals.....	19
Thermocouple connections.....	62
Thermocouple measurement.....	46
Thermocouple simulation.....	55
Tools.....	
Additional Info.....	147
Additional Stability Check.....	147
Alarm.....	147
Damping.....	147
Function Info.....	147
Leak / Stability Test.....	147
Quick Access Buttons.....	147
Ramp.....	147
Resolution.....	147
Scaling.....	147
Step.....	147
Touch screen.....	25
Trademarks.....	190
Trim fieldbus instrument.....	145
Trim HART instrument.....	143
Typographical conventions.....	8

U

Unpacking.....	6
User interface.....	
Buttons.....	30
Controls.....	30
Date/Time fields.....	32
Editable fields.....	32
Hardware focus indicator.....	30
Modes.....	29
Numeric fields.....	32
Spinning tool.....	32
Text fields.....	32
User Interface mode.....	
Calibrator.....	67
Communicator.....	117
Data Logger.....	108
Documenting Calibrator.....	69
Meter.....	65
Settings.....	176
User sensor.....	
Create new.....	156
Update data.....	159
Use.....	158
User sensors.....	155
User-defined.....	
Calibration points.....	153
Pressure unit.....	43
Steps.....	153
Transfer functions.....	151

V

Voltage generation.....	58
Voltage measurement.....	49

W

Warnings.....	
Battery pack.....	14
Charger.....	14
Electrical measurement and generation.....	11
Pressure Measurement.....	11
Smart instruments.....	13
WEEE.....	186
Wireless communication.....	
Bluetooth.....	168
Connect devices.....	170
Connection security.....	169
Information window.....	172
Pair devices.....	170
Requirements.....	169
Troubleshooting.....	174
Work Order View Mode.....	104