
BEAMEX CWSI client

RELEASE NOTE

Software Update v1.2.3 for Beamex CWSI Client.....	2
Software Update v1.2.2 for Beamex CWSI Client.....	3
Software Update v1.2.1 for Beamex CWSI Client.....	4
Software Update v1.2.0 for Beamex CWSI Client.....	5
Software Update v1.1.0 for Beamex CWSI Client.....	6
Software Update v1.0.0 for Beamex CWSI Client.....	7

Product Software Update for Beamex CWSI Client	Version 1.2.3
Related Products Beamex Calibration Web Service Interface Beamex CMX	Release date 18 May, 2018
Short description Software Update for Beamex CWSI Client	

Software Update v1.2.3 for Beamex CWSI Client

A new software update for the Beamex Calibration Web Service Interface Client. For more information see CMX Installation Guide, CMX User Guide and CWSI Help.

Changes

The version 1.2.3 has the following changes compared to the previous version (1.2.2):

New Main Features:

1. N/A

Fixes:

1. Removed the zero character from end of free fields to avoid problems in B3 export.
2. Fixed issue with Required firmware version when Mobile Security is enabled. Now versions with only zeros as minor, like v3.00 are supported.

Other Changes:

1. N/A

Known Issues

1. On Windows Vista, the Port combo box under Serial Communication tab is not automatically refreshed when adding/removing a USB-to-Serial converter. Current workaround is to connect the USB-to-Serial converter prior to starting the CWSI Client.

Product Software Update for Beamex CWSI Client	Version 1.2.2
Related Products Beamex Calibration Web Service Interface Beamex CMX	Release date 15th March, 2018
Short description Software Update for Beamex CWSI Client	

Software Update v1.2.2 for Beamex CWSI Client

A new software update for the Beamex Calibration Web Service Interface Client. For more information see CMX Installation Guide, CMX User Guide and CWSI Help.

Changes

The version 1.2.2 has the following changes compared to the previous version (1.2.1):

New Main Features:

1. N/A

Other Changes:

1. Corrections to an error where MC6 calibrator's system time was not synchronized to the client computer time when communicating with MC6 via CWSI.

Known Issues

1. On Windows Vista, the Port combo box under Serial Communication tab is not automatically refreshed when adding/removing a USB-to-Serial converter. Current workaround is to connect the USB-to-Serial converter prior to starting the CWSI Client.

Product Software Update for Beamex CWSI Client	Version 1.2.1
Related Products Beamex Calibration Web Service Interface Beamex CMX	Release date 7th March, 2018
Short description Software Update for Beamex CWSI Client	

Software Update v1.2.1 for Beamex CWSI Client

A new software update for the Beamex Calibration Web Service Interface Client. For more information see CMX Installation Guide, CMX User Guide and CWSI Help

You can find the software update on the CMX v2.11.2 installation DVD.

Changes

The version 1.2.1 has the following changes compared to the previous version (1.2.0):

New Main Features:

1. N/A

Other Changes:

1. Better support for the resolution information has been added. It is now possible to determine if the resolution is retrieved from the entered value or if a fixed resolution was used.
2. Better support for Reference due date information and rules depending on these has been added.
3. A reading conversion problem have been addressed in this release that caused the instrument to differ even when it did not.

Known Issues

1. On Windows Vista, the Port combo box under Serial Communication tab is not automatically refreshed when adding/removing a USB-to-Serial converter. Current workaround is to connect the USB-to-Serial converter prior to starting the CWSI Client.

Product Software Update for Beamex CWSI Client	Version 1.2.0
Related Products Beamex Calibration Web Service Interface Beamex CMX	Release date 4 th December, 2017
Short description Software Update for Beamex CWSI Client	

Software Update v1.2.0 for Beamex CWSI Client

A new software update for the Beamex Calibration Web Service Interface Client. For more information see CMX Installation Guide, CMX User Guide and CWSI Help

You can find the software update on the CMX v2.11 installation DVD.

Changes

The version 1.2.0 has the following changes compared to the previous version (1.1.0):

New Main Features:

1. Added support for the new **Mobile Security Plus** features. Please see CMX v2.11 release notes for more information.

Other Changes:

1. N/A

Known Issues

1. On Windows Vista, the Port combo box under Serial Communication tab is not automatically refreshed when adding/removing a USB-to-Serial converter. Current workaround is to connect the USB-to-Serial converter prior to starting the CWSI Client.

Product Software Update for Beamex CWSI Client	Version 1.1.0
Related Products Beamex Calibration Web Service Interface Beamex CMX	Release date 27 th May, 2016
Short description Software Update for Beamex CWSI Client	

Software Update v1.1.0 for Beamex CWSI Client

A new software update for the Beamex Calibration Web Service Interface Client. For more information see CMX Installation Guide, CMX User Guide and CWSI Help

You can find the software update on the CMX v2.10 installation DVD.

Changes

The version 1.1.0 has the following changes compared to the previous version (1.0.0):

New Main Features:

- Added support for the new **Beamex bMobile** application. Please see our web site or CMX v2.10 release notes for more information.

Other Changes:

- Updated .NET Framework dependency to version 4.6
- CWSI assemblies and executables are now digitally signed using an SHA-256 algorithm as a result of the Windows enforcement of Authenticode code signing and timestamping (<http://social.technet.microsoft.com/wiki/contents/articles/32288.windows-enforcement-of-authenticode-code-signing-and-timestamping.aspx>).

Known Issues

- On Windows Vista, the Port combo box under Serial Communication tab is not automatically refreshed when adding/removing a USB-to-Serial converter. Current workaround is to connect the USB-to-Serial converter prior to starting the CWSI Client.

Product Software Update for Beamex CWSI Client	Version 1.0.0
Related Products Beamex Calibration Web Service Interface Beamex CMX	Release date 12 th June, 2015
Short description Software Update for Beamex CWSI Client	

Software Update v1.0.0 for Beamex CWSI Client

Initial release.

Calibration Web Service Interface (CWSI), enables the possibility to communicate with supported calibrators over Wide Area Networks. Supported Calibrators are:

- Beamex MC6
- Beamex MC4
- Beamex CMX for Pocket PC
- A number of 3rd party calibrators supporting standard FCINTF protocol. For more information about supported calibrators, contact Beamex.

CWSI introduces two new modules: the CWSI Client, which is locally installed on every computer that is physically connected to a calibrator and the CWSI Server, which is a common gateway for all CWSI Clients. In addition to this, CWSI support is implemented into the CMX Client, which enables CMX to communicate with calibrators connected to CWSI clients via the familiar Send/Receive window.

For more information see CMX Installation Guide, CMX User Guide and CWSI Help

Known Issues

- On Windows Vista, the Port combo box under Serial Communication tab is not automatically refreshed when adding/removing a USB-to-Serial converter. Current workaround is to connect the USB-to-Serial converter prior to starting the CWSI Client.